Verify Check

Fuel Master switch	ON - guard down
Engine Feed	NORM
EPU	NORM
Eng Cont	. PRI - guard down
Throttle	CUTOFF
Landing Gear	DOWN & LOCKED
Hook switch	UP
Master Arm	OFF
Air Source	NORM

Before Engine Start

Main PWR BATT
FLCS RLY lightON
FLCS PWR TEST TEST and HOLD
ACFT BATT TO FLCS lightON
FLCS PMG lightON
FLCS PWR lightON
FLCS RLY light OFF
Main PWRMAIN
ELEC SYS lightON
HYD/OIL PRESS lightON
FLCS RLY lightON
SEC lightON
ENGINE lightON
EPU GEN light OFF
EPU PMG lightOFF
Communications ALL TO UHF BACKUP
Canopy CLOSED
Chocks IN PLACE
COM1 & COM2 vol. knobSET

Engine Start

JFS switch	START 2
JFS light	ON within 30s
	. ADVANCE IDLE at 25% RPM
SEC caution light	OFF at 20% RPM
	OFF at 60% RPM
	CONFIRM OFF at 55% RPM
HYD/OIL PRESS caution ligh	itOFF between 15% and
70% RPM	
Fuel flow	700 - 1700 PPH
OIL PRESS gauge	MIN 15 PSI
	GREATER 94%
	62 - 80%
	BELOW 650
	AT 12 O'CLOCK
	ON

After Engine Start

NC
ET
FF
FF
FF
LD
ΙG
LD
NC
NC
NC

EPU Check

EPU Safety Pin	OFF 100% ENGAGED OFF
EPU switch	
EPU GEN TEST switchEP	
EPU AIR light	ON
EPU GEN & PMG lights	
FLCS PWR lights	
EPU RUN light	
THROTTLE	