TELIUM SDK

SDK6.5.3 Release Note

Reference: ICO-ETU-09-0851-PP
Date: 2009-12-16

From: Pascal PLASSE
To: All SDK users

TABLE OF CONTENTS

1. PURPOSE OF THE DOCUMENT

This document describes the evolutions since the SDK6.5.2.

2. TERMINALS COMPATIBILITY

2.1 CGUI

This SDK is compatible with CGUI (Color and Graphic User Interface). To use it, you have to install the CGUI add-on version 1.6.1 or newer.

2.2 TELIUM 1

The following terminals are compatible with this SDK release:

- EFT30
- EFT SMART
- TWIN
- UCM
- ML30
- CAD30
- SMART2

2.3 TELIUM 2

The following terminals are compatible with this SDK release:

- ICT220
- ICT250 is managed with extension cards. Only the following are currently managed (only one feature available by option):
  - Card option 1 : SCR2 (=CAM2)
  - Card option 2 : GPRS / µSD / Contactless
  - Card option 5 : µSD / 2nd RS232
- SPM

2.4 HANDHELD TERMINALS

This SDK is compatible with these products:

- EFT930
- EFT930 BL2
  - GPRS,
  - GPRS Contactless,
  - GPRS Color,
  - GPRS Contactless Color;
  - Bluetooth,
  - Bluetooth Contactless,
  - Bluetooth Color;
  - EFT930 BCC (Bluetooth Color Contactless).

3. **HIGHLIGHTED POINTS**

3.1 **ISC350**

The ISC350 is not managed by this package. For this terminal you need to use the SDK 7.0 Preliminary 2 for ISC350.

3.2 **DIR SYSTEM VERSION DOWNGRADE**

It is not possible to downgrade from a system managing directories (catalogue XXX_DIR.mYY) to a system which not manage directories (catalogue XXX.mYY).

3.3 **EFT930BL2 SYSTEM VERSION DOWNGRADE**

It is not possible to downgrade from the EFT930 BL2 system version embedded in the SDK 6.4.2 (or newer), to an older one. This downgrade is blocked. It is due to a change of the time base (1 s to 125 ms).

3.4 **SERVICE NUMBERS**

Service numbers from 1 to 100 and from 7680 à 8191 are reserved for Ingenico internal use.

3.5 **DOCUMENTATION**

The folders under <Your Install Directory>\Document have changed. Now, most part of the documentation is inside the file SDK_TELIUM.chm.

3.6 **EFT930 WHICH EMBED 8MO OF FLASH**

It is not possible to use this SDK on EFT930 which have only 8 Mo of flash.

4. TELIUM SYSTEM

No evolution: version of Telium System: **08.35**.
New version of Telium Manager: **54.03**.

Following points are delivered in this release.

| 6436 | Possible blockage fixed: When a handheld terminal was connected to a base, it could be blocked if the pack system was bigger than 2 MB |
| 5120 | When there was no system pack in the base, the version uploaded was 99.99 |

5. TELIUM MANAGER

No evolution: version of Telium Manager: **54.03**.

DLL SECURITY

No evolution: version of DLL Security is: **03.10**.

6. DLL HARDWARE

No evolution: version of DLL Hardware is: **02.32**.

7. SCHEMES

No evolution: version is **03.06**.

8. LINKLAYER

No evolution: version of Link Layer is: **03.10**.

9. PACK IP

No evolution: version of Pack IP is: **03.05**.

10. FTP

No evolution: version of FTP is: **01.17**.

11. SSL

No evolution: version of SSL is: **01.48**.

12. AVL (ADDED VALUE LIBRARIES)

No evolution: version of AVL: **01.07**.

13. SDK

13.1 FONTS

No evolution: version of the fonts is: **01.09**.

13.2 SIMULATOR

No evolution: version of the Simulator: **02.05**.

[END OF DOCUMENTATION]