

## **TELIUM SDK**

# SDK6.5.1 Release Note

Reference: ICO-ETU-09-0747-PP

Date: 2009-11-26

From: Pascal PLASSE

To: All SDK users



## **TABLE OF CONTENTS**

1.	PUF	RPOSE OF THE DOCUMENT	1
2.	TER	RMINALS COMPATIBILITY	1
2 2 2	.1 .2 .3 .4	CGUI TELIUM 1 TELIUM 2 HANDHELD TERMINALS	. 1 . 1
3.	HIG	GHLIGHTED POINTS	2
3 3 3	.1 .2 .3 .4 .5	ISC350 DIR SYSTEM VERSION DOWNGRADE EFT930BL2 SYSTEM VERSION DOWNGRADE SERVICE NUMBERS DOCUMENTATION EFT930 WHICH EMBED 8MO OF FLASH	2 2 2 2
4.	TEL	IUM SYSTEM	3
4	.1 .2 .3	THUNDER ICTXXX BLUETOOTH HANDHELD TERMINALS	. 3
5.	TEL	IUM MANAGER	3
DL	L SEC	CURITY	3
6.	DLL	L HARDWARE	3
7.	SCH	HEMES	3
8.	LIN	IKLAYER	3
9.	PAC	CK IP	3
10.	FTP	)	4
11.	SSL		4
12.	AVL	L (ADDED VALUE LIBRARIES)	4
13.	SDK	K	4
1	3.1	FONTS	



## 1. PURPOSE OF THE DOCUMENT

This document describes the evolutions since the SDK6.5 which is the previous one.

### 2. TERMINALS COMPATIBILITY

#### 2.1 **CGUI**

This SDK is compatible with CGUI (Color and Graphic User Interface). To use it, you have to install the CGUI add-on version 1.6.1 or newer.

#### 2.2 **TELIUM 1**

The following terminals are compatible with this SDK release:

- EFT30
- EFT SMART
- TWIN
- UCM
- ML30
- CAD30
- SMART2

#### 2.3 **TELIUM 2**

The following terminals are compatible with this SDK release:

- ICT220
- ICT250 is managed with extension cards. Only the following are currently managed (only one feature available by option):
  - Card option 1 : SCR2 (=CAM2)
  - o Card option 2: GPRS / µSD / Contactless
  - o Card option 5: µSD / 2<sup>nd</sup> RS232
- SPM

#### 2.4 HANDHELD TERMINALS

This SDK is compatible with these products:

- EFT930
- EFT930 BL2
  - o GPRS,
  - o GPRS Contactless,
  - o GPRS Color,
  - o GPRS Contactless Color;
  - o Bluetooth,
  - o Bluetooth Contactless,
  - o Bluetooth Color;
  - o EFT930 BCC (Bluetooth Color Contactless).



## 3. HIGHLIGHTED POINTS

#### 3.1 **ISC350**

The ISC350 is not managed by this package. For this terminal you need to use the SDK 7.0 Preliminary for ISC350.

#### 3.2 DIR SYSTEM VERSION DOWNGRADE

It is not possible to downgrade from a system managing directories (catalogue XXX\_DIR.mYY) to a system which not manage directories (catalogue XXX.mYY).

#### 3.3 EFT930BL2 SYSTEM VERSION DOWNGRADE

It is not possible to downgrade from the EFT930 BL2 system version embedded in the SDK 6.4.2 (or newer), to an older one. This downgrade is blocked. It is due to a change of the time base (1 s to 125 ms).

#### 3.4 **SERVICE NUMBERS**

Service numbers from 1 to 100 and from 7680 à 8191 are reserved for Ingenico internal use.

#### 3.5 **DOCUMENTATION**

The folders under <Your Install Directory>\Document have changed. Now, most part of the documentation is inside the file SDK\_TELIUM.chm.

#### 3.6 <u>EFT930 WHICH EMBED 8MO OF FLASH</u>

It is not possible to use this SDK on EFT930 which have only 8 Mo of flash.



## 4. **TELIUM SYSTEM**

New version of Telium System: **08.34**.

Following points are delivered in this release.

#### 4.1 THUNDER

Diagnostic added to know active IT active after a power cut.

#### **4.2 ICTXXX**

Fix of a reset during the printing (problem occurred more frequently with SEIKO

printers that could be installed in future ICTs)

#### 4.3 BLUETOOTH HANDHELD TERMINALS

Fix of a problem of configuration of a serial port with format command when a fopen

on the COM port was done previously

6305 It was not possible to do a Bluetooth association as long as the battery charge is

under 1%

#### 5. TELIUM MANAGER

New version of Telium Manager: **54.02**.

Following points are delivered in this release.

It is now possible to manage 10 numbers amount

5721 IDSA added (IDSA is a identifier sent by the bank server)

6204 ICT GPRS equipment type added (= 170)

Fix for colour display sequence code using defdisplaypattern (in particular used

during contactless transactions on ML30CC)

#### **DLL SECURITY**

New version of DLL Security is: 03.10.

Only internal point added.

#### 6. DLL HARDWARE

New version of DLL Hardware is: **02.32**.

Following points are delivered in this release.

5308 On color display, if CGUI DLL don't exist, it works like before

#### 7. SCHEMES

No evolution: version is **03.06**.

#### 8. LINKLAYER

No evolution: version of Link Layer is: **03.10**.

#### 9. PACK IP

No evolution: version of Pack IP is: **03.05**.



## 10. FTP

No evolution: version of FTP is: **01.17**.

## 11. SSL

New version of SSL is: 01.48.

Lowering of the base period for SSL\_Read()

It was not possible to empty the cache memory of the SSL server

5590 DLL SSL traces removed

## 12. AVL (ADDED VALUE LIBRARIES)

New version of AVL: 01.07.

Following point are delivered in this release.

6193 Barcode norms EAN8 and EAN13 managed

6311 It is now possible to print 2D barcode PDF417 with rotation 90; 180 and 270 °

## 13. SDK

#### **13.1 FONTS**

Version of the fonts is: **01.09**.

6268 Added sizes \_dPOLICE8x12\_ (based upon dLARGE), \_dPOLICE7x8 and

\_dPOLICE5x7\_\_ (based upon SMALL) for the fonts

Width of size \_FIXED\_WIDTH\_ was too large for some characters

#### 13.2 SIMULATOR

Version of the Simulator: **02.05**.

[END OF DOCUMENTATION]

SDK6.5.1 Release Note