


Low lighting and saturated lighting scenarios

Scenario


Example

Low lighting, tool partially visible:
annotate based on the expected shape of the instrument.




The green outline shows annotations for a partially visible tool. Annotate the visible pixels, considering the instrument's expected shape.

Low lighting, tool not visible:
do not annotate



The image has low visibility such that instruments visible in previous frames are completely obscured. Do not annotate unseen instruments.

Saturated lighting, tool not visible:
do not annotate



The image has low visibility due to saturated lighting, making the instruments indiscernible. Do not annotate.