

C302
TRANSFER CASE ASSEMBLY

PIN	CIRCUIT	CIRCUIT FUNCTION
1	770 (WH)	Motor Position 4
2	764 (BN/WH)	Motor Position 3
3	763 (OG/WH)	Motor Position 2
4	777 (YE)	4 Wheel Drive Control Module to Transfer Case Assembly
5	771 (VT/YE)	Motor Position 5
6	762 (YE/WH)	Motor Position 1
7	778 (OG)	4 Wheel Drive Control Module to Transfer Case Assembly
8	–	NOT USED

CONNECTOR REFERENCE LIST

CONNECTOR	SECTION-PAGE
C112	29-5
C202	24-8
C286	62-6
C291	14-3