-1


15
F2.16
10A
P91
Central Junction
Box (CJB)
15) Hot in start or
run
10
C270c
S222
640
20 RD/YE
2
C220c
A30
Instrument cluster
36) Safety belt indi-
cator
41) Microprocessor
41
36
3
C220b
469
22 LG
3
C212
469
20 LG
1
C323
N474
Safety belt switch
3
2
2) Safety belt re-
tracted
3) Safety belt ex-
tended
2
C323
57
20 BK
S309
G402