4R70W



C109

OUTPUT SHAFT SPEED (OSS) SENSOR

PIN	CIRCUIT	CIRCUIT FUNCTION
1	359 (GY/RD)	Signal Return
2	136 (DB/YE)	Output Shaft Speed (OSS) Sensor Signal to PCM

CONNECTOR REFERENCE LIST

CONNECTOR	SECTION-PAGE
C154	24-12, 25-12