93-1 REVERSING LAMPS

2002 EXPEDITION/NAVIGATOR

For diagnostic information, refer to Section 417-01 of the Workshop Manual.