

C129

TURBINE SHAFT SPEED (TSS) SENSOR

PIN	CIRCUIT	CIRCUIT FUNCTION
1	970 (DG/WH)	Turbine Shaft Speed (TSS) Sensor Signal Return
2	359 (GY/RD)	Signal Return



C136

OUTPUT SHAFT SPEED (OSS) SENSOR

PIN	CIRCUIT	CIRCUIT FUNCTION
1	136 (DB/YE)	Output Shaft Speed (OSS) Sensor Signal to PCM
2	359 (GY/RD)	Signal Return

CONNECTOR REFERENCE LIST

CONNECTOR	SECTION-PAGE
C1027	22-20, 24-20, 24-23, 25-20, 25-23, 27-16