93-1 REVERSING LAMPS

2001 EXPLORER/MOUNTAINEER

For diagnostic information, refer to Section 417-01 of the Workshop Manual.

* 4.0L
** 5.0L