CONNECTOR REFERENCE LIST

CONNECTOR	SECTION-PAGE
C185	23-8
C1012	23-11



C118

OUTPUT SHAFT SPEED (OSS) SENSOR

PIN	CIRCUIT	CIRCUIT FUNCTION
1	359 (GY/RD)	Signal Return
2	136 (DB/YE)	Output Shaft Speed Sensor Signal to PCM