Wiper/washer switch -8

Component testing procedure

Circuit to test	Connect self–powered test light or ohmmeter to terminals	Move switch to these positions	A good switch will indicate
Rheostat (variable intermittent wipe)	1 and 10	1	1 kΩ
		2	10 kΩ
		3	20 kΩ
		4	30 kΩ
		5	40 kΩ
		6	47 kΩ
Single wipe Front wiper	6 and 9	Single wipe	Closed circuit
		Off	Open circuit
		Intermittent	Open circuit
		Normal	Closed circuit
		Fast	Open circuit
Intermittent wipe Front wiper	6 and 10	Single wipe	Open circuit
		Off	Open circuit
		Intermittent	Closed circuit
		Normal	Open circuit
		Fast	Open circuit
	7 and 9	Single wipe	Open circuit
		Off	Closed circuit
		Intermittent	Closed circuit
		Normal	Open circuit
		Fast	Open circuit
Normal wipe Front wiper	6 and 9	Single wipe	Closed circuit
		Off	Open circuit
		Intermittent	Open circuit
		Normal	Closed circuit
		Fast	Open circuit
Fast wipe Front wiper	6 and 8	Single wipe	Open circuit
		Off	Open circuit
		Intermittent	Open circuit
		Normal	Open circuit
		Fast	Closed circuit
Front washer	6 and 2	Off	Closed circuit
		Front washer on	Open circuit
	2 and 3	Off	Open circuit
		Front washer on	Closed circuit
Rear washer	6 and 5	Off	Open circuit
		Rear wiper on	Closed circuit
		Rear washer on	Closed circuit
	3 and 4	Off	Open circuit
		Rear wiper on	Open circuit
		Rear washer on	Closed circuit