

C197
MASS AIR FLOW (MAF) SENSOR

PIN	CIRCUIT	CIRCUIT FUNCTION
1	359 (GY/RD)	Sensor Signal Return
2	361 (RD)	Power (Hot in Start or Run)
3	969 (BK)	MAF Ground
4	968 (TN/LB)	MAF Return
5	967 (LB/RD)	PCM to MAF Sensor
6	743 (GY)	Intake Air Temperature (IAT) Sensor

CONNECTOR REFERENCE LIST

CONNECTOR	SECTION-PAGE
C110	29-5
C132	29-5
C232	14-3
C251	60-3
C451	25-14