66-1 WARNING CHIME

2001 TOWN CAR

For diagnostic information refer to Section 413-09 of the Workshop Manual

REVISED



LCM will sound a warning if the key is left in the ignition, safety belt is not buckled, headlamps are left on or if it receives a request by the instrument cluster through the SCP network. Door ajar information is received via the multiplex communication network.

Refer to Location Index, Cell 152, for Component, Connector, Splice, Ground and Base Part Number descriptions and locations.