COMPONENT TESTING PROCEDURE

TO TEST	Connect Self-Powered Test Lamp or Ohmmeter to Terminals	Move Switch to These Positions	A Good Switch Will Indicate
Up Switch Circuit	3 and 5	Up	Closed Circuit
Down Switch Circuit	4 and 1	Up and at Rest	Closed Circuit
	3 and 1	Down	Closed Circuit
	2 and 5	Down and at Rest	Closed Circuit

SCHEMATIC



TERMINALS