4R70W



C187

OUTPUT SHAFT SPEED (OSS) SENSOR

PIN	CIRCUIT	CIRCUIT FUNCTION
1	1202 (BN/LG)	Signal Return
2	136 (DB/YE)	Output Shaft Speed Sensor (OSS) Signal to PCM

CONNECTOR REFERENCE LIST

CONNECTOR	SECTION-PAGE
C141	22-18, 23-11, 24-11, 25-11, 26-14, 27-13
C174	22-16, 23-9, 24-9, 25-9, 26-10, 27-11
C189	34-6