COMPONENT TESTING PROCEDURE

Connect Battery Positive and Negative to Terminals	Check Continuity from Terminals:	Continuity Will Be:
1 and 2	3 to 4 and 3 to 5	From 3 to 5 only
–	1 to All Others	To 2 only
–	3 to All Others	To 4 only

TERMINALS



SCHEMATIC