TERMINALS



COMPONENT TESTING PROCEDURE

TO TEST	Connect Self-Powered Test Lamp or Ohmmeter to Terminals	Move Switch to These Positions	A Good Switch Will Indicate
Power Lock	2 and 4 4 and 5	Lock Unlock	Closed Circuit Closed Circuit

SCHEMATIC