87-1 AUTOLAMPS/DELAYED EXIT

2001 WINDSTAR

For diagnostic information, refer to Section 417-01 of the Workshop Manual.