**4R70W**




**C187**

**OUTPUT SHAFT SPEED (OSS) SENSOR**

| PIN | CIRCUIT | CIRCUIT FUNCTION |
|---|---|---|
| 1 | 1202 (BN/LG) | Signal Return |
| 2 | 136 (DB/YE) | Output Shaft Speed (OSS) Sensor Signal to PCM |

**CONNECTOR REFERENCE LIST**

| CONNECTOR | SECTION-PAGE |
|---|---|
| C174 | 24-9, 25-9 |
| C243 | 13-28 |
| C1026 | 24-11 |