4R70W



C187
OUTPUT SHAFT SPEED (OSS) SENSOR

PIN	CIRCUIT	CIRCUIT FUNCTION
1	1202 (BN/LG)	Signal Return
2	136 (DB/YE)	Output Shaft Speed (OSS) Sensor Signal to PCM

CONNECTOR REFERENCE LIST

CONNECTOR	SECTION-PAGE
C174	24-9, 25-9
C243	13-28
C1026	24-11