COMPONENT TESTING PROCEDURE

TO TEST	Connect Self-Powered Test Lamp or Ohmmeter to Terminals	Move Switch to These Positions	A Good Switch Will Indicate
Lock Switch Circuit	3 and 4	Lock	Closed Circuit
	1 and 2	Lock and at Rest	Closed Circuit
Unlock Switch Circuit	3 and 2	Unlock	Closed Circuit
	5 and 4	Unlock and at Rest	Closed Circuit

SCHEMATIC



TERMINALS



REVISED