

C100
INTERMEDIATE SHAFT SPEED (ISS) SENSOR

PIN	CIRCUIT	CIRCUIT FUNCTION
1	134 (GY/OG)	ISS to Powertrain Control Module (PCM)
2	359 (GY/RD)	Signal Return



C109
OUTPUT SHAFT SPEED (OSS) SENSOR

PIN	CIRCUIT	CIRCUIT FUNCTION
1	136 (DB/YE)	OSS to Powertrain Control Module (PCM)
2	359 (GY/RD)	Signal Return

CONNECTOR REFERENCE LIST

CONNECTOR	SECTION-PAGE
C111	24-11
C202	24-8
C287	62-6