Auxiliary relay box 2, As of 2/18/02