COMPONENT TESTING PROCEDURE

TO TEST	Connect Self-Powered Test Light or Ohmmeter to Terminals	Move Switch to These Positions	A Good Switch Will Indicate
One Touch Down Circuit	8 (C501) and 4 (C501)	One-Touch Down	Closed Circuit

WINDOW SWITCH SCHEMATIC