

C1028

TURBINE SHAFT SPEED (TSS) SENSOR

PIN	CIRCUIT	CIRCUIT FUNCTION
1	359 (GY/RD)	Sensor Signal Return
2	970 (DG/WH)	Turbine Shaft Speed (TSS) Sensor to Powertrain Control Module (PCM)

CONNECTOR REFERENCE LIST

CONNECTOR	SECTION-PAGE
C1018	23-16
C1032	23-13