COMPONENT TESTING PROCEDURE

TO TEST	Connect Self-Powered Test Light or Ohmmeter to Terminals	Move Switch to These Positions	A Good Switch Will Indicate
Power and Ground Checks Before Any Other Tests	2 and 2	All Four Window Switches (all positions)	Open Circuit
	2 and 6, 7, 4, 3, 7, 3, 5, 4	All Four Window Switches (at rest)	Closed Circuit

COMPONENT TESTING PROCEDURE

TO TEST	Connect Self-Powered Test Light or Ohmmeter to Terminals	Move Switch to These Positions	A Good Switch Will Indicate
Left Front Window Circuit	2 and 6	Up	Closed Circuit
	2 and 7	Down	Closed Circuit
Right Front Window Circuit	2 and 4	Up	Closed Circuit
	2 and 3	Down	Closed Circuit
Left Rear Window Circuit	2 and 7	Up	Closed Circuit
	2 and 6	Down	Closed Circuit
Right Rear Window Circuit	2 and 5	Up	Closed Circuit
	2 and 4	Down	Closed Circuit
Window Lock Switch	2 and 3	Window Lock Switch Toward Door	Closed Circuit
		Window Lock Switch Away From Door	Open Circuit
Automatic Switch	2 and 5	Automatic Switch (Engaged)	Closed Circuit
		Automatic Switch (At Rest)	Open Circuit