# MODIFIED CERTIFICATION LABEL INSTALLATION

**AFFECTED VEHICLES: CERTAIN 2001 MODEL YEAR E-SERIES CUTAWAY MODELS**

1. Locate and wipe clean the original certification label on the driver's door B-pillar above the striker.
2. NOTE: To help properly align the ***new*** label over the original, the ***new*** label is the same dimension as the original and is clear except for the upper right corner which contains the revised information. Line up the outside edges and be sure the revised information covers only the words "BY FORD MOTOR COMPANY", and the GVWR and REAR GAWR ratings.

   Peel the backing from the ***new*** label and very carefully position and apply the ***new*** label over the original label. See Figure 1.





**FIGURE 1**

Ford Motor Company
CPR © 2001 FORD MOTOR COMPANY
DEARBORN, MICHIGAN 48121
08/01