Ford Motor Company

June 2001

TO: All Ford and Lincoln/Mercury Dealers

SUBJECT: Safety Recall 01S20 - All 2000 and certain 2001 Model Year Windstar vehicles equipped with Adjustable Accelerator/Brake Pedal Option – Driver Floor Mat Interference

AFFECTED VEHICLES

All 2000 and certain 2001 Model Year Windstar equipped with Adjustable Accelerator/Brake Pedal Option built at the Oakville Assembly Plant from February 8, 2000 through December 4, 2000.

SAFETY CONCERN

In certain adjusted positions, the pedal in the affected vehicles could contact, and potentially hang up on, the driver's floor mat when the accelerator pedal is fully depressed.

SERVICE ACTION

Dealers must remove the original driver's side front floor mat and install the newly released Windstar front floor mat. This must be done on all of the affected vehicles. Ford Motor Company is also providing a complimentary front passenger floor mat to ensure that the front mats match and that the customer is completely satisfied. The Dealer must mutilate and scrap the mats that are replaced so they cannot be reused.

Dealers are encouraged to replace the floor mats in a "no wait" process to enhance customer satisfaction and help to minimize the inconvenience the customer will experience.

PLEASE NOTE

Correct all vehicles in stock before delivery. Federal law requires dealers to complete any outstanding safety recall service before a new vehicle is delivered to the buyer or lessee. Violation of this requirement by a dealer could result in a civil penalty of up to $5,000 per vehicle.

ATTACHMENTS

Attachment I: Administrative Information
Attachment II: Labor Allowances and Parts Ordering Information
Customer Notification Letter

© Copyright 2001 Ford Motor Company

QUESTIONS?

Claims Information:……..……...1-800-423-8851
Other (Dealer Only) Recall Questions:……..……...1-800-325-5621

Sincerely,



Ann O'Neill
Director
Vehicle Service and Programs

© Copyright 2001 Ford Motor Company

Safety Recall 01S20
All 2000/certain 2001 Windstar equipped with Adjustable Pedal Option
Driver Floor Mat interference

OASIS

You must use OASIS to determine if a vehicle is eligible for this recall.

PROMPTLY CORRECT

Promptly correct all affected vehicles in the online Involved Unit Listings available on QCDealer.com or in the Ford Dealer Consolidated Communicator (FDCC). Also, correct other eligible vehicles which are brought to your dealership.

DEALER-OWNER CONTACT

Immediately contact any affected owner whose name is not on the list. Give the owner a copy of the Owner Letter and schedule a service date.

REGIONAL CONTACT

Advise regional office if an owner:

- cannot be contacted.
- Does not make a service date.

CLAIMS PREPARATION AND SUBMISSION

- Enter claims using DWE.
- Refer to ACESII manual for claims preparation and submission information.

OWNER REFUNDS

Ford Motor Company will only refund owner-paid repairs made before the date of the Owner Letter (or after the date of the Owner Letter if an emergency repair was made away from the servicing dealer). Refer to ACESII manual for refund information.

RENTAL CARS

Rental cars are not available for this program.

© Copyright 2001 Ford Motor Company

Safety Recall 01S20
All 2000/certain 2001 Windstar equipped with Adjustable Pedal Option
Driver Floor Mat Interference

LABOR ALLOWANCES

Description	Labor Operation	Labor Time
Replace Front Mats	01S20B	0.3 Hour
Administrative Allowance	Misc. Expense Code "ADMIN"	0.1 Hour

PARTS REQUIREMENTS

Parts Ordering Information

Parts will not be direct shipped for this recall. Order your parts requirement through normal order processing channels as noted below:

Stock Orders	Effective immediately	Normal order process
Interim Orders	Effective immediately	Normal order process
Emergency Orders	First 30 days after launch	Call 1-800-325-5621
Emergency Orders	31 days after launch	Normal order process

Part Number	Description	Quantity
1F2Z-1613086-GAA	Standard – Front Floor Mat Kit Medium Graphite	1
1F2Z-1613086-HAA	Standard – Front Floor Mat Kit Medium Parchment	1

© Copyright 2001 Ford Motor Company

Safety Recall 01S20
All 2000/certain 2001 Windstar equipped with Adjustable Pedal Option
Driver Floor Mat Interference

Part Number	Description	Quantity
1F2Z-1613086-JAA	**Limited** – Front Floor Mat Kit, Medium Parchment **MUST CALL 1-800-325-5621 FOR ALL ORDER TYPES for this Part Number ONLY**	1

NOTE: After removing the original floor mats, MUTILATE AND SCRAP SO THEY CANNOT BE REUSED**.**

ORDER INFORMATION

DOR/COR number 50248 identifies parts ordered for this campaign through the Special Service Support Center (1-800-325-5621).

DEALER PRICE

For latest prices, refer to:

- DOES II
- Updated Price Book

© Copyright 2001 Ford Motor Company

Ford Motor Company

Ford Motor Company
P. O. Box 1904
Dearborn, Michigan 48121

June 2001

01S20

Mr. John Sample
123 Main Street
Anywhere, USA 12345

Your Vehicle Identification Number: 12345678901234567

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

Ford Motor Company has decided that a defect, which relates to motor vehicle safety exists in certain 2000 and 2001 Model year Windstar equipped with the adjustable pedal option.

What the safety issue is …

In some adjusted positions, the accelerator pedal on your vehicle could contact, and potentially hang up on, the floor mat when the pedal is depressed fully.

What Ford Motor Company and your dealer will do ...

The dealer will replace both front driver and passenger side floor mats in your vehicle. The Dealer is required to mutilate and scrap the old floor mats. These will not be returned to you.

Ford Motor Company will replace your floor mats free of charge (parts and labor). Owners who are affected by this recall are requested to return their vehicle to their dealer for replacement of the driver and passenger side front floor mats. Ford Motor Company is providing a complimentary passenger floor mat to ensure that the front mats match.

How long will it take?

The time needed for this repair is less than one-half day. However, due to service scheduling requirements, the dealer may need your vehicle for a longer period of time.

What we are asking you to do …

Call your dealer without delay. Ask for a service date and whether parts are in stock for Safety Recall 01S20.

If your dealer does not have the parts in stock, they can be ordered before scheduling your service date. Parts would be expected to arrive within a week after ordering. When you bring your vehicle in, show the dealer this letter. If you misplace this letter, your dealer will still do the work, free of charge.

© Copyright 2001 Ford Motor Company

If you've already paid for this service …

If you paid to have this service done before the date of this letter, Ford is offering a full refund. For the refund, please give your paid original receipt to your dealer. To avoid delays, do not send receipts to Ford Motor Company.

If you've changed address or sold the vehicle …

Please fill out the enclosed prepaid postcard and mail it to us if you have changed address or sold the vehicle.

If you have concerns …

If you have trouble getting your vehicle repaired promptly and without charge, please contact your dealership's Service Manager. If you still need assistance, please contact the Ford Motor Company Customer Relationship Center and one of our representatives will be happy to assist you:

CALL: (866) 436-7332

Office Hours: (Eastern Standard Time)

Monday-Friday: 8am - 11pm Saturday 9am – 6pm
Hearing impaired call (800) 232-2952
TDD for the hearing impaired.

Or you may contact us through the internet …

www.ownerconnection.com

If you still have trouble getting your vehicle repaired and without charge, you may write the Administrator, National Highway Traffic Safety Administration, 400 Seventh Street, S. W., Washington, D. C. 20590 or call the toll free Auto Safety Hotline 1-888-327-4236 or 1-800-424-9393.

Quality Care service is there for you all year round.

QualityCare™ at your service

Quality Care is the commitment of Ford Motor Company and its dealerships to provide you with a superior service and ownership experience. While we regret the inconvenience caused by this program, we stand committed with our dealers to assist you with all of your automotive service needs. With our nationwide dealer network, we're here to ensure you receive Quality Care service so that your vehicle maintains peak performance throughout your ownership experience.

We pride ourselves on becoming the world's leading Consumer Company for automotive products and services. Thank you for your attention to this important matter.

Sincerely,

Ann O'Neill
Director
Vehicle Service and Programs

© Copyright 2001 Ford Motor Company