Ford Motor Company

A. R. O'Neill
Director
Vehicle Service and Programs
Ford Customer Service Division

Ford Motor Company
P. O. Box 1904
Dearborn, Michigan 48121

December 2000

TO: All Ford and Lincoln Mercury Dealers

SUBJECT: **Owner Notification Program 00B58:** Certain 2001 Model Year Explorer Sport Trac 4x2 Vehicles – Powertrain Calibration Update

OASIS: Yes
OWNER LIST: Yes
PARTS RETURN: No
PROGRAM TERMS: This program will be in effect until August 31, 2001, regardless of Mileage.

AFFECTED VEHICLES

Certain 2001 model year Explorer Sport Trac 4X2 vehicles equipped with automatic transmission, and built at the Louisville Assembly Plant through 5/18/2000.

REASON FOR PROGRAM

Although Ford does not advocate driving at vehicle maximum speed, it is possible for the affected vehicles to exceed the design maximum speed. Prolonged operation above the design maximum speed could cause damage to the transmission output shaft bushing or seal. Therefore, we are recommending that customers return their vehicles to have the Powertrain Control Module (PCM) updated with a revised calibration that will maintain vehicle top speed within the intended design level.

SERVICE ACTION

The vehicle Powertrain Control Module (PCM) will be reprogrammed.

ATTACHMENTS

Attachment I: Administrative Information
Attachment II: Labor Allowances and Parts Ordering Information
Attachment III: Technical Information
Customer Notification Letter

QUESTIONS?

Claims Information: 1-800-423-8851
Other Program Questions: 1-800-325-5621

Sincerely,



Ann O'Neill
Director
Vehicle Service and Programs

Owner Notification Program 00B58
Certain 2001 Explorer Sport Trac Vehicles with Automatic Transmission
Powertrain Calibration Update

OASIS

You must use OASIS to determine if a vehicle is eligible for this program.

PLEASE NOTE

Correct all vehicles in stock before delivery.

DEALER-OWNER CONTACT

Promptly correct all affected vehicles on the enclosed list and other eligible vehicles which are brought to your dealership.

CLAIMS PREPARATION AND SUBMISSION

- Enter claims using DWE.
- Refer to ACESII manual for claims preparation and submission information.

OWNER REFUNDS

Refunds do not apply to the program.

RENTAL CARS

Rental cars are not approved for this program.

Owner Notification Program 00B58
Certain 2001 Explorer Sport Trac Vehicles with Automatic Transmission
Powertrain Calibration Update

LABOR ALLOWANCES

Description	Labor Operation	Labor Time
Unable to recalibrate – latest level already installed	00B58A	0.3 Hours
Update Powertrain Control Module (PCM) calibration	00B58B	0.4 Hours
Administrative Allowance	Misc. Expense Code "ADMIN"	0.1 Hour

PARTS REQUIREMENTS

Part Number	Description	Quantity
FPS-8262	Authorized Modification Label*	1

* Label orders come in packages of 25

Ford Motor Company

Ford Motor Company
P. O. Box 1904
Dearborn, Michigan 48121
1-800-392-3673
www.ownerconnection.com

December 2000

00B58

Mr. John Sample
123 Main Street
Anywhere, USA 12345

Your Vehicle Identification Number: 12345678901234567

Ford Motor Company is providing a no-charge service to owners of 2001 Explorer Sport Trac vehicles equipped with automatic transmission, built at the Louisville Assembly Plant.

Reason For This Program

Although Ford does not advocate driving at vehicle maximum speed, it is possible for the affected vehicles to exceed design maximum speed. Prolonged operation above the design maximum speed could cause damage to the transmission output shaft bushing or seal. Therefore, we are recommending that customers return their vehicles to have the Powertrain Control Module (PCM) calibration updated to maintain vehicle top speed within intended design level.

What *Ford Motor Company* and your dealer will do…

Ford Motor Company will repair your vehicle free of charge. Owners who are affected by this owner notification are asked to return their vehicles to their dealer for a powertrain calibration update. The updated calibration will insure that the vehicle operates within the design maximum speed.

This program will be in effect until August 31, 2001, regardless of mileage.

What we are asking you to do…

Call your dealer without delay. Provide the dealer with your Vehicle Identification Number (located at the beginning of this letter). Ask for a service date for Owner Notification Program 00B58.

How long will it take….

The time needed for this repair is less than one-half day. However, due to service scheduling issues, your dealer may need your vehicle for a longer period of time. Please call your dealer for a service date.

When you bring your vehicle in, show the dealer this letter. If you misplace this letter, your dealer will still do the work, free of charge.

If you've changed address or sold the vehicle…

Please fill out the enclosed prepaid postcard and mail it to us if you have changed address or sold the vehicle.

If you have concerns…

If you have trouble getting your vehicle repaired promptly and without charge, please contact your dealership Service Manager. If you still need assistance, please contact the Ford Motor Company Customer Relationship Center and one of our representatives will be happy to assist you:

CALL: (800) 392-3673
(800) 232-5952 (TDD for the Hearing Impaired)

Office Hours: (Eastern Standard Time)

Monday-Friday: 8am - 11pm

Saturday: 9am - 6pm

or you may contact us through the Internet at:
www.ownerconnection.com
Our current response time to Internet inquiries is three business days.

Quality Care service is there for you all year round.

QualityCare™ at your service

Quality Care is the commitment of Ford Motor Company and its dealerships to provide you with a superior service and ownership experience. While we regret the inconvenience caused by this program, we stand committed with our dealers to assist you with all of your automotive service needs. With our nationwide dealer network, we're here to ensure you receive Quality Care service so that your vehicle maintains peak performance throughout your ownership experience.

We pride ourselves on becoming the world's leading consumer company for automotive products and services. Again, we are sorry for the inconvenience. Thank you for your attention to this important matter.

Sincerely,



Ann O'Neill
Director
Vehicle Service and Programs