Ford Motor Company

A. R. O'Neill
Director
Vehicle Service and Programs
48121
Ford Customer Service Division

Ford Motor Company
P. O. Box 1904
Dearborn, Michigan

February 2001

TO: All Ford and Lincoln Mercury Dealers

SUBJECT: Special Field Action 00L11: Certain 2000 and 2001 Model Year Expedition and Navigator and Certain 2001 Model Year F-150 Super Cab, Taurus, and Sable Vehicles – Revised Owner's Guide Child Tether Instructions

OASIS:	No – Owner's Guide Page Labels or Owner's Guides will be mailed directly to owners
OWNER LIST:	No
PARTS RETURN:	No
PROGRAM TERMS:	This program will be in effect until September 31, 2001, regardless of mileage.

AFFECTED VEHICLES

- Certain 2000 and 2001 Expedition and Navigator vehicles built at the Michigan Truck Assembly Plant from Job #1, 2000 through September 21, 2000
- Certain 2001 Taurus and Sable vehicles built at both the Atlanta Assembly Plant and the Chicago Assembly Plant from Job #1, 2001 through November 11, 2000
- Certain 2001 F-150 Super Cab vehicles built at the Norfolk Assembly Plant, Kansas City Assembly Plant, Ontario Truck Assembly Plant, and the Cuautitlan Assembly Plant from Job #1, 2001 through September 22, 2000

NON-COMPLIANCE

The affected vehicles do not meet the requirements of FMVSS 225, Child Restraint Anchorage Systems, for the following reasons:

- Expedition and Navigator: the Owner's Guides do not identify the locations of seat positions equipped with tether anchorages and do not include instructions on how to properly secure child seat tether strap to tether anchorages in the vehicle.
- Taurus and Sable: the Owner's Guides do not identify the center rear seat position as having lower anchorages that are compatible with child seat latches.
- F-150: the Owner's Guides do not contain complete written instructions on how to properly secure child seat tether strap to tether anchorages in a Super Cab vehicle.

SERVICE ACTION

- Expedition and Navigator: no dealer service action required; these customers will be sent a new Owner's Guide and asked to discard their old one.
- Taurus and Sable: an Owner's Guide page label with the correct information will be mailed to owners of the affected vehicles.
- F-150: no dealer service action required; these customers will be sent a new Owner's Guide and asked to discard their old one.

PLEASE NOTE:

Owners will be given instructions either to replace their current Owner's Guide with a new one mailed to them or in the case of the Taurus and Sable, to place a label directly over an existing Owner's Guide page. If a Taurus or Sable owner chooses, this label may be installed by service personnel.

ADDITIONAL OWNER'S GUIDE PAGE LABELS OR OWNER'S GUIDES

Additional labels (for customers who prefer to have this label installed at the dealership and arrive without the label) or Owner's Guides (for dealer stock units) may be ordered as follows:

Call 1-800-325-5621

- Ask for an additional Owner's Guide page label or Owner's Guide for program 00L11
- Provide vehicle model year and make to obtain the correct Owner's Guide page label or Owner's Guide

ATTACHMENTS

Attachment I: Administrative Information
Attachment II: Labor Allowances and Parts Ordering Information
Attachment III: Technical Information
Customer Notification Letter

QUESTIONS?

Claims Information:…… 1-800-423-8851
Other (Dealer Only) Recall Questions:…… 1-800-325-5621

Sincerely,



Ann O'Neill
Director
Vehicle Service and Programs

Special Field Action: 00L11
Certain 2000 and 2001 Model Year Expedition and Navigator and
Certain 2001 Model Year F-150 Super Cab, Taurus, and Sable Vehicles
Revised Owner's Guide Child Tether Instructions

OASIS

OASIS will not be activated for this program.

PLEASE NOTE

Correct all vehicles in stock before delivery. Federal law requires dealers to complete any outstanding safety recall service before a new vehicle is delivered to the buyer or lessee. Violation of this requirement by a dealer could result in a civil penalty of up to $5,000 per vehicle.

DEALER-OWNER CONTACT

An owner list will not be provided.

CLAIMS PREPARATION AND SUBMISSION

- Enter claims using DWE.
- Refer to ACESII manual for claims preparation and submission information.

Special Field Action: 00L11
Certain 2000 and 2001 Model Year Expedition and Navigator and
Certain 2001 Model Year F-150 Super Cab, Taurus, and Sable Vehicles
Revised Owner's Guide Child Tether Instructions

LABOR ALLOWANCES

Description	Labor Operation	Labor Time
For Expedition, F-150 Super Cab, or Navigator vehicle: Insert New Owner's Guide (Dealer Stock Units Only)	00L11B	0.1 Hour
For Taurus or Sable vehicle: Install Owner's Guide page label over existing page in Owner's Guide if requested by customer or if required for a dealer stock unit	00L11C	0.2 Hour

PARTS REQUIREMENTS

Ordering Instructions for Additional Owner's Guide Page Labels or Owner's Guides

Owner's Guide page labels and new Owner's Guides for this program are being sent directly to customers of the affected vehicles. Additional labels (for customers who prefer to have this label installed at the dealership and arrive without the label) or Owner's Guides (for dealer stock units) may be ordered as follows:

Call 1-800-325-5621

- Ask for an additional Owner's Guide page label or Owner's Guide for program 00L11
- Provide vehicle model year and make to obtain the correct Owner's Guide page label or Owner's Guide

DEALER PRICE

Dealers will not be charged for the Owner's Guide page labels or Owner's Guides ordered under this program.

Ford Motor Company

Ford Motor Company
P. O. Box 1904
Dearborn, Michigan 48121
1-800-392-3673

March 2001

Your Vehicle Identification Number: 12345678901234567
00L11
F-150
Dear Mr. John Sample:

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

Ford Motor Company has decided that certain 2001 model year F-150 Super Cab vehicles fail to conform to the requirements specified in the Federal Motor Vehicle Safety Standard (FMVSS) No. 225 Child Restraint Anchorage Systems.

It has come to our attention that the Owner's Guide of your F-150 Super Cab vehicle contains incomplete information. We apologize for this inconvenience and want to correct this condition. Our commitment, together with your Ford dealer, is to provide you with the highest level of service and support possible.

What the non-compliance issue is…	The Owner's Guide for your 2001 model year F-150 Super Cab vehicle does not provide the procedure for securing child seats to the child tether anchorages as required by Safety Standard No. 225. Without the proper Owner's Guide procedure, the potential exists to improperly secure the child seat tether strap to the tether anchorages.
What we are asking you to do…	Please discard your old Owner's Guide and replace it with the one included with this letter.
If you have changed address or sold the vehicle…	Please fill out the enclosed prepaid postcard and mail it to us if you have changed address or sold the vehicle.

If you have concerns…

If you have questions, please contact the Ford Motor Company Customer Relationship Center and one of our representatives will be happy to assist you:

CALL: (800) 392-3673
(800) 232-5952 (TDD for the Hearing Impaired)

Office Hours: (Eastern Standard Time)
Monday-Friday: 8am - 11pm
Saturday: 9am - 6pm

or you may contact us through the Internet at:
www.ownerconnection.com
Our current response time to Internet inquiries is three business days.

You also may send a complaint to the Administrator, National Highway Traffic Safety Administration, 400 Seventh Street, S. W., Washington, D. C. 20590 or call the toll free Auto Safety Hotline at 1-888-327-4236 or 1-800-424-9393 (residents of Washington D.C. must call 1-888-327-4236).

Quality Care service is there for you all year round.

Quality Care is the commitment of Ford Motor Company and its dealerships to provide you with a superior service and ownership experience. While we regret the inconvenience caused by this notification, we stand committed with our Ford and Lincoln Mercury dealers to assist you with all of your automotive service needs. With our nationwide dealer network, we are here to ensure you receive Quality Care service so that your vehicle maintains peak performance throughout your ownership experience.

We pride ourselves on becoming the world's leading consumer company for automotive products and services. Thank you for your attention to this important matter.

Sincerely,



Ann O'Neill
Director
Vehicle Service and Programs