BRAKES—HYDRAULIC—GEL-LIKE SUBSTANCE FLOATING ON TOP OF FLUID IN MASTER CYLINDER	Article No. 02-6-3

FORD: 1999-2002 SUPER DUTY F-53 STRIPPED CHAS.
1999 F-800
2000-2002 F-650, F-750

This TSB is being republished in it's entirety to update the affected vehicles.

ISSUE

A clear gel-like substance in the hydraulic brake master cylinder reservoir may appear on some vehicles. This substance is a silicone base lubricant used during assembly of the master cylinder. It will float on top of the brake hydraulic fluid in the master cylinder.

ACTION

Advise the customer that this condition is considered normal and in no way affects the operation of the brake system. It does not require any service action.

OTHER APPLICABLE ARTICLES: NONE
SUPERSEDES: 00-8-2
WARRANTY STATUS: INFORMATION ONLY
OASIS CODES: 301000, 390000

Copyright © 2002 Ford Motor Company