WHEEL—INCREASED WHEEL NUT AND STUD SIZE—SERVICE TIP	Article No. 99-26-3

FORD: 2000 EXPEDITION, F-150

LINCOLN: 2000 NAVIGATOR

ISSUE

All 2000 F-150s (excluding F-150 equipped with 7-stud wheels and the 7700 payload group), Expeditions and Navigators built on/or after November 27, 1999 will have revised wheel stud and wheel nut diameters. The wheel studs and wheel nuts will have increased thread diameter from 12mm to 14mm. This change will include revised wheels, center wheel ornaments, hubs, brake rotors, wheel nuts and a new longer (by 12.7 cm/5″) two-piece lug wrench.

ACTION

The 14mm wheel nut will require a 21mm socket instead of the 19mm socket used on the 12mm wheel nuts. The torque specification for the 14mm wheel nuts is 200 N•m (150 lb-ft). A torque wrench must be used to insure proper torque is reached. The torque specification for the 12mm wheel nut will remain at 133 N•m (100 lb-ft).

NOTE

THESE NEW (14mm) PARTS ARE NOT INTERCHANGEABLE WITH THE PREVIOUS (12mm) PARTS.

OTHER APPLICABLE ARTICLES: NONE
WARRANTY STATUS: INFORMATION ONLY
OASIS CODES: 301000, 303000, 304000, 306000, 307000, 390000