Continental Tire Owner Notification Letter

Ford Vehicle Owner Notification


MM/DD/YYYY

Vehicle ID#
J A SAMPLE
APARTMENT 1
123 MAIN STREET
ANYWHERE, US 12345-6789

Dear Valued Customer:

This notice is being sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act. Continental Tire North America, Inc., ("CTNA") has decided that a defect, which relates to motor vehicle safety, exists in P275/60R17 Grabber AW and ContiTrac AW tires manufactured by CTNA between March 1999 and October 2000. Affected tires can be identified as shown below:

Size: P275/60R17
Tire Name: General Grabber AW or Continental ContiTrac AW
DOT Serial Numbers showing date of manufacture:
General Grabber AW - DOT ADT044T109 through ADT044T4400
Continental ContiTrac AW – DOT ADT044U109 through ADT044U4400



The DOT serial number certifies the tire manufacturer's compliance with the U.S. Department of Transportation tire safety standards. Tires made for use in the United States have the DOT serial number located on one sidewall of the tire and will be located near the rim. Typically tires that come on new vehicles will have the DOT serial number sidewall mounted on the inside. Starting with the year 2000, four numbers are used for the Date of Manufacture, first two numbers identify the week and the last two numbers identify the year of manufacture.

Prior to year 2000 three numbers are used for the date of manufacture, first two numbers identify the week and the last number identifies the year of manufacture. To identify tires manufactured in the 90's a decade symbol (a triangle on its side) is located at the end of the DOT serial number.

© Copyright 2002 Ford Motor Company

Example: 109 manufacturing date means the tire was manufactured during the 10th week of 1999 or 4400 manufacturing date means the tire was manufactured during the 44th week of 2000. The tires covered under this recall program were manufactured during and between these time periods. Tires are not covered under this recall program with a manufacturing date of 099 and earlier or 4500 and later.

Your model year 2000 or 2001 two-wheel drive Ford Expedition or Lincoln Navigator may have come equipped with the subject tires. This notice is being sent to inform you of the CTNA tire recall program to replace the subject tires on these vehicles. CTNA and Ford/Lincoln Mercury vehicle dealers will be working together to minimize any inconvenience to you.

Why we are taking this action:
We are initiating this tire recall program because a belt separation may occur that could cause a section of the tread and belt package to detach from the tire casing, which could cause minor vehicle damage or a vehicle crash. Typically, the condition is detected when vehicle owners notice irregular tread wear, vibration or noise.

What will CTNA do for you:
CTNA will replace affected P275/60R17 Grabber AW and ContiTrac AW tires manufactured between March 1999 and October 2000 with approved tire(s) at no charge, including mounting and balance. CTNA will provide detailed instructions to dealers concerning the selection of appropriate replacement tires. Replacement tires are available at authorized Ford/Lincoln Mercury dealers. As noted above, there will be no charge for the replacement tire(s) or for installation**, if done before April 1, 2003.**

What should you do:
Please make an appointment with the nearest Ford or Lincoln Mercury dealer to have your tires inspected and if necessary replaced. Based on the dealer's inspection, your tires will not be replaced if the tires on your vehicle are not affected by this recall program. If your tires do need replaced under this recall program, the labor time necessary to perform this tire replacement is approximately four hours. In order to reduce the chance that a tread detachment will occur before the tires are replaced under this recall program, and consistent with recommended tire maintenance practices, make sure to keep the tires properly inflated and avoid overloading the vehicle. For your information, the correct tire pressure for your Ford Expedition or Lincoln Navigator is 26 psi for the front tires and 33 psi for the rear tires. If you notice irregular tread wear, vibration or noise immediately contact your nearest Ford or Mercury dealer for further instructions.

You may also call CTNA Consumer Relations at 1-800-847-3349 or visit www.continentaltire.com or www.generaltire.com on line. If you need assistance locating a Ford or Lincoln Mercury dealer please call the Ford Customer Relationship Center at 1-800-392-3673 or the Lincoln Customer Relationship Center at 1-800-521-4140 or visit www.dealerconnection.com on line.

© Copyright 2002 Ford Motor Company

If you have previously replaced one or more P275/60R17 Grabber AW or ContiTrac AW tires, between August 19, 2001 and October 10, 2002, CTNA will reimburse the cost of the tires, mounting, balancing, and applicable sales tax equal to the purchase price, if replaced with Continental or General brand tires. Otherwise total reimbursement for the cost of the tire(s) will not exceed suggested retail price of a ContiTrac AW size P275/60R17 or Grabber AW P275/60R17 tire ($110 USA + tax.). You may obtain a Reimbursement Request Form #CR29 O.I. by calling CTNA Consumer Relations at 1-800-847-3349 or visit www.continentaltire.com or www.generaltire.com on line. To be eligible for reimbursement, the Reimbursement Request Form #CR29 O.I. must be received by CTNA before December 31, 2002. You will be required to submit proof of purchase to be eligible for the reimbursement.

In the event you believe this remedy is inadequate, you may submit a complaint to the Administrator, National Highway Traffic Safety Administration, 400 Seventh Street, SW, Washington, DC 20590, or call the toll free Auto Safety Hotline at 1-888-327-4236 (Washington, DC residents may call 202-366-0123.)

We apologize for any inconvenience that this action may cause you. Our goal is to replace your tires if necessary with the least amount of inconvenience to you. Thank you in advance for your cooperation.

Sincerely,

Continental North America, Inc.
1800 Continental Blvd.
Charlotte, NC 28273

© Copyright 2002 Ford Motor Company