Ford Motor Company

A. R. O'Neill
Director
Vehicle Service and Programs
48121
Ford Customer Service Division

Ford Motor Company
P. O. Box 1904
Dearborn, Michigan

December 2001

TO: All Ford and Lincoln Mercury Dealers

SUBJECT: Emissions Recall 01E16: Certain 2000/2001 F150 and Navigator vehicles built with 5.4L engine **-** Incorrect HEGO Sensor

AFFECTED VEHICLES

Certain 2000/2001 F150 and Navigator vehicles built with 5.4L engine that received a replacement HEGO sensor during service (note: only 76 vehicles affected).

REASON FOR FIELD SERVICE ACTION

In the affected vehicles, an incorrect HEGO sensor may have been installed during service. Vehicles with the incorrect HEGO sensor installed may exceed applicable exhaust emissions standards.

SERVICE ACTION

The Dealers should inspect any affected vehicle that may have received an incorrect HEGO sensor during service and replace it with the correct one.

NOTE: The State of California and the Commonwealth of Massachusetts require the completion of emission recall repairs prior to vehicle registration renewal. For vehicles registered in these states, please provide the owner with a Vehicle Emission Recall Proof of Correction certificate after the service action has been performed. (These certificates may be obtained by contacting your regional office.)

ATTACHMENTS

Attachment I: Administrative Information
Attachment II: Labor Allowances and Parts Ordering Information
Attachment III: Technical Information
Customer Letter(s)

QUESTIONS?

Claims Information: ……1-800-423-8851
Other Field Service Action (Dealers Only) Questions: ……1-800-325-5621

Sincerely,

Ann O'Neill
Director
Vehicle Service and Programs

© Copyright 2001 Ford Motor Company

EMISSIONS RECALL 01E16
Certain 2000/2001 F150 and Navigator vehicles built with 5.4L engine
Incorrect HEGO Sensor

OASIS

You must use OASIS to determine if a vehicle is eligible for this recall.

PROMPTLY CORRECT

Promptly correct all affected vehicles on your dealer Online Involved Unit Listing available on QCDealer.com. Also, correct other affected vehicles identified in OASIS which are brought to your dealership.

DEALER-OWNER CONTACT

Immediately contact any affected owner whose name is not on the list but whose vehicle is identified in OASIS. Give the owner a copy of the Owner Letter and schedule a service date.

NOTE: These dealer listings may contain customer names and addresses obtained from Motor Vehicle Registration Records. The use of such motor vehicle registration data for any purpose other than in connection with this field service action is a violation of law in several states/provinces/countries. Accordingly, limit the use of this listing to the follow-up necessary to complete this action.

REGIONAL CONTACT

Advise regional office if an owner:

- cannot be contacted.
- does not make a service date.

CLAIMS PREPARATION AND SUBMISSION

- Enter claims using DWE.
- Refer to ACESII manual for claims preparation and submission information.

OWNER REFUNDS

Ford Motor Company will only refund owner-paid repairs made before the date of the owner letter (or after the date of the owner letter if an emergency repair was made away from the servicing dealer). Refer to ACESII manual for refund information.

RENTAL CARS

Rental vehicles are not authorized for this program.

© Copyright 2001 Ford Motor Company

EMISSIONS RECALL 01E16
Certain 2000/2001 F150 and Navigator vehicles built with 5.4L engine
Incorrect HEGO Sensor

LABOR ALLOWANCES

Description	Labor Operation	Labor Time
Replace HEGO sensor – 2000 Navigator 5.4L	**01E16B**	0.8 Hour
Replace HEGO sensor - 2000/2001 F150 5.4L MFI	**01E16C**	0.9 Hour
Replace HEGO sensor - 2000/2001 F150 5.4L SC	**01E16D**	0.5Hour
Administrative Allowance	Misc. Expense Code "ADMIN"	0.1 Hour

PARTS REQUIREMENTS / ORDERING INFORMATION

Parts will not be direct shipped for this Field Service Action. Order your parts requirement through normal order processing channels as noted below:

All Order Types Effective immediately Normal order process

Part Number	Description	Quantity
XC2Z-9F472-AA	HEGO sensor	1

NOTE: There are ONLY 76 total vehicles affected by this action.

DEALER PRICE

For latest prices, refer to DOES II or updated price book.

PARTS RETENTION

Follow the provisions of the Warranty and Policy Manual for “Parts Retention and Return Procedures”.

EXCESS STOCK RETURN

Excess stock returned for credit must have been purchased from Ford Customer Service Division in accordance with Policy Procedure Bulletin 4000.

© Copyright 2001 Ford Motor Company

Ford Motor Company

A. R. O'Neill
Director
Vehicle Service and Programs
48121
Ford Customer Service Division

Ford Motor Company
P. O. Box 1904
Dearborn, Michigan

January 2002

For **Owners in CA and MA only**: Emissions Recall 01E16

Mr. John Sample
123 Main Street
Anywhere, CA or MA 12345

Your Vehicle Identification Number: 12345678901234567

Ford Motor Company values you as a customer and is committed to vehicle quality and the environment. Therefore, we are voluntarily recalling certain 2000/2001 F150 and Navigator vehicles serviced with the wrong HEGO Sensor. Your vehicle may be releasing air pollutants that exceed California or Massachusetts emission standards.

What is the emission concern?

In some of the affected vehicles, the wrong HEGO sensor may have been installed during service. The incorrect HEGO sensor may cause applicable exhaust emissions standards to be exceeded due to the potential for incorrect fuel/air ratios.

What Ford Motor Company and your dealer will do...

Ford Motor Company will repair your vehicle free of charge (parts and labor). Owners who are affected by this Field Service Action are requested to return their vehicle to their dealer for installation of the correct HEGO sensor. This service should have no effect on your vehicle, except to provide the correct emissions control strategy.

If you do not have this service done:

- Your emissions warranty may be reduced.
- Your vehicle may not pass emissions or smog tests that may be required in your area.
- Your state Department of Motor Vehicles may not renew your vehicle's registration.

How long will it take?

The time needed for this repair is less than one-half day. However, due to service scheduling issues, your dealer may need your vehicle for a longer period of time.

© Copyright 2001 Ford Motor Company

What we are asking you to do…

Call your dealer without delay. Provide the dealer with your Vehicle Identification Number (located at the beginning of this letter). Ask for a service date and whether parts are in stock for Emissions Recall 01E16. If you do not have a servicing dealer, please access www.dealerconnection.com for dealer addresses, maps, and driving instructions.

If your dealer does not have the parts in stock, they can be ordered before scheduling your service date. Parts would be expected to arrive within a week after ordering.

When you bring your vehicle in, show the dealer this letter. If you misplace this letter, your dealer will still do the work, free of charge.

If you have already paid for this service…

If you paid to have this service done before the date of this letter, Ford is offering a full refund. For the refund, please give your paid original receipt to your dealer. To avoid delays, do not send receipts to Ford Motor Company.

If you have changed address or sold the vehicle…

Please fill out the enclosed prepaid postcard and mail it to us so we can update our records. If you have sold the vehicle, the information you provide on the postcard will be used to notify the new owner about this Field Service Action.

If you have concerns….

If you have trouble getting your vehicle repaired promptly and without charge, please contact your dealership Service Manager for assistance. If you still have concerns, please contact the Ford Motor Company Customer Relationship Center and one of our representatives will be happy to assist you.

CALL: (866) 436-7332 or
(800) 232-5952 (TDD for the Hearing Impaired)

Office Hours: (Eastern Standard Time)
Monday-Friday: 8AM – 11PM, Saturday, 8AM – 6PM

Or you may contact us through the Internet …

www.ownerconnection.com

Vehicles registered in California or Massachusetts…

The State of California and the Commonwealth of Massachusetts require the completion of emissions recall repairs prior to vehicle registration renewal. Your vehicle is subject to these requirements.

When your dealer completes this emissions recall repair, you will receive a Vehicle Emission Recall Proof of Correction certificate. **Please make sure that you receive a certificate from your dealer and that you have it with you when you renew your vehicle registration.**

It is also important for you to know that the certificate should be

© Copyright 2001 Ford Motor Company

returned to the Department of Motor Vehicles (DMV) only if it is requested by the DMV. Otherwise, this certificate is to be held by you for your records.


In order to ensure your full protection under emissions warranty provisions and to avoid any inconvenience when renewing your registration, it is recommended that you have your vehicle serviced as soon as possible. Failure to do so could be determined as lack of proper maintenance of your vehicle.

Quality Care service is there for you all year round.

Quality Care is the commitment of Ford Motor Company and its dealerships to provide you with a superior service and ownership experience. While we regret the inconvenience caused by this program, we stand committed with our dealers to assist you with all of your automotive service needs. With our nationwide dealer network, we're here to ensure you receive Quality Care service so that your vehicle maintains peak performance throughout your ownership experience.

We pride ourselves on becoming the world's leading consumer company for automotive products and services. Again, we are sorry for the inconvenience. Thank you for your attention to this important matter.

Sincerely,



Ann O'Neill
Director
Vehicle Service and Programs

© Copyright 2001 Ford Motor Company

Ford Motor Company

A. R. O'Neill
Director
Vehicle Service and Programs
48121
Ford Customer Service Division

Ford Motor Company
P. O. Box 1904
Dearborn, Michigan

December 2001

Emissions Recall 01E16

Mr. John Sample
123 Main Street
Anywhere, USA 12345

Your Vehicle Identification Number: 12345678901234567

Ford Motor Company values you as a customer and is committed to vehicle quality and the environment. Therefore, we are voluntarily recalling certain 2000/2001 F150 and Navigator vehicles serviced with the wrong HEGO Sensor.

What is the emission concern?

In some of the affected vehicles, the wrong HEGO sensor may have been installed during service. The incorrect HEGO sensor may cause applicable exhaust emissions standards to be exceeded due to the potential for incorrect fuel/air ratios.

What Ford Motor Company and your dealer will do...

Ford Motor Company will repair your vehicle free of charge (parts and labor). Owners who are affected by this recall are requested to return their vehicle to their dealer for installation of the correct HEGO sensor. This service should have no effect on your vehicle, except to provide the correct emissions control strategy.

If you do not have this service done:

- Your emissions warranty may be reduced.
- Your vehicle may not pass emissions or smog tests that may be required in your area.

How long will it take?

The time needed for this repair is less than one-half day. However, due to service scheduling issues, your dealer may need your vehicle for a longer period of time.

What we are asking You to do…

Call your dealer without delay. Provide the dealer with you Vehicle Identification Number (located at the beginning of this letter). Ask for a service date and whether parts are in stock for Emission Recall 01E16. If you do not have a servicing dealer, please access www.dealerconnection.com for dealer addresses, map, and driving instructions.

© Copyright 2001 Ford Motor Company

If your dealer does not have parts in stock, they can be ordered before scheduling your service date. Parts would be expected to arrive within a week after ordering.
When you bring your vehicle in, show the dealer this letter. If you misplace this letter, your dealer will still do the work, free of charge.

If you've already paid for this service…

If you paid to have this service done before the date of this letter, Ford is offering a full refund. For the refund, please give your paid original receipt to your dealer. To avoid delays, do not send receipts to Ford Motor Company.

If you've changed address or sold the vehicle…

Please fill out the enclosed prepaid postcard and mail it to us so we can update our records. if you have sold the vehicle, the information you provide on the postcard will be used to notify the new owner about this program.

If you have concerns….

If you have trouble getting your vehicle repaired promptly and without charge, please contact your dealership Service Manager for assistance. If you still have concerns, please contact the Ford Motor Company Customer Relationship Center and one of our representatives will be happy to assist you.

CALL (866) 436-7332 or (800) 232-5952 (TDD for the Hearing Impaired)

Office Hours: (Eastern Standard Time)
Monday-Friday: 8AM – 11PM, Saturday, 8AM – 6PM

Or you may contact us through the Internet …

www.ownerconnection.com


Please have your vehicle serviced promptly to maintain full emission warranty coverage

Quality Care service is there for you all year round.

Quality Care is the commitment of Ford Motor Company and its dealerships to provide you with a superior service and ownership experience. While we regret the inconvenience caused by this program, we stand committed with our dealers to assist you with all of your automotive service needs. With our nationwide dealer network, we're here to ensure you receive Quality Care service so that your vehicle maintains peak performance throughout your ownership experience.

We pride ourselves on becoming the world's leading consumer company for automotive products and services. Again, we are sorry for the inconvenience. Thank you for your attention to this important matter.

Sincerely,



Ann O'Neill
Director
Vehicle Service and Programs

© Copyright 2001 Ford Motor Company