Ford Motor Company

Ann O'Neill
Director
Vehicle Service and Programs
48121
Ford Customer Service Division

Ford Motor Company
P. O. Box 1904
Dearborn, Michigan

November 2001

TO: All Ford and Lincoln Mercury Dealers

SUBJECT: Customer Satisfaction Program 01B86: Supplement #1
1. Revised Technical Instructions

REFERENCE: Customer Satisfaction Program 01B86, dated October, 2001: Certain 2001 Lincoln Town Car Vehicles--Hybrid Electronic Cluster (HEC) Module Inspection/Replacement

REFERENCE: Dealer Announcement dated 12/17/98, Lincoln Commitment Special Handling Procedure

NOTE: Customer Satisfaction Program 01B86 is being republished in its entirety. 01B86 Supplement #1 supersedes 01B86. Please discard all previous copies and replace with this supplement.

OASIS :	Yes
OWNER LIST:	Yes
PARTS RETURN:	Yes
PROGRAM TERMS:	This program will be in effect until October 31, 2002, regardless of mileage.

REASON FOR THIS SUPPLEMENT

This bulletin is being re-published to correct the technical instructions in Attachment III. The I.D. numbers listed in the original technical instructions were incorrect. The correct I.D. numbers have been added to the technical instructions to better assist the dealers in identifying affected HEC Modules.

AFFECTED VEHICLES

Certain 2001 Lincoln Town Car vehicles built at the Wixom Assembly Plant from March 30, 2001 through June 13, 2001

REASON FOR PROGRAM

In some of the affected vehicles, under certain conditions, initialization errors for the Passive Anti-Theft System (PATS) may occur in the Hybrid Electronic Cluster during a key cycle from OFF to RUN, RUN to START and START to RUN. This condition may cause an intermittent no start.

SERVICE ACTION

The dealer must inspect the I.D. number for the Hybrid Electronic Cluster (HEC) module. If the HEC module is one of the affected modules the HEC module will be replaced and all vehicle PATS keys will be reprogrammed. Owners will be notified to bring all keys to the dealership on their scheduled service date. If the HEC module is not one of the suspect modules then no action is required and the vehicle can be returned to the customer.

SPECIAL HANDLING PROCEDURE

The Special Handling Procedure has been activated for all Town Car owners affected by this program. Please see dealer announcement dated 12/17/98, Special Handling Procedure. The special handling procedure provides additional allowance to enable dealers to offer Town Car owners convenient vehicle handling.

Lincoln Mercury is asking for your support and the cooperation of your sales and service teams to make this a positive experience for our Town Car customers, many of whom are new to the Lincoln family.

ATTACHMENTS

Attachment I: Administrative Information
Attachment II: Labor Allowances and Parts Ordering Information
Attachment III: Technical Information
Customer notification Letter

QUESTIONS?

Claims Information: 1-800-423-8851
Other Program Questions: 1-800-325-5621

Sincerely,



Ann O'Neill
Director
Vehicle Service and Programs

Customer Satisfaction Program 01B86-S1
Certain 2001 Lincoln Town Car Vehicles
HEC Module Inspection/Replacement

OASIS

You must use OASIS to determine if a vehicle is eligible for this program.

PLEASE NOTE

Correct all vehicles in stock before delivery.

DEALER-OWNER CONTACT

Promptly correct all affected vehicles on your dealer Online Involved Unit Listing available on QCDealer.com. Also, correct other affected vehicles identified in OASIS which are brought to your dealership

NOTE: These dealer listings may contain customer names and addresses obtained from Motor Vehicle Registration Records. The use of such motor vehicle registration data for any purpose other than in connection with this field service action is a violation of law in several states/provinces/countries. Accordingly, limit the use of this listing to the follow-up necessary to complete this action.

Note: Owners should receive the "Special Handling Procedure". To familiarize yourself, please review "Special Handling Procedure" before calling customers.

CLAIMS PREPARATION AND SUBMISSION

- Enter claims using DWE.
- Refer to ACESII manual for claims preparation and submission information.

To claim for "Special Handling", follow the instructions on page two of dealer announcement dated 12/17/98.

OWNER REFUNDS

Ford Motor Company will only refund owner-paid repairs made before the date of the Owner Letter (or after the date of the Owner Letter if an emergency repair was made away from the servicing dealer.) Refer to ACESII manual for refund information.

Program Code:	01B86
Misc. Expense:	REFUND
Misc. Expense:	ADMIN
Misc. Expense:	0.2 Hr.

RENTAL CARS

Rental vehicles are approved per guidelines in the "Special Handling Procedure."

Customer Satisfaction Program 01B86-S1
Certain 2001 Lincoln Town Car Vehicles
HEC Module Inspection/Replacement

LABOR ALLOWANCES

Description	Labor Operation	Labor Time
Inspect the I.D. Number of the Hybrid Electronic Cluster (HEC) Module-Return Vehicle to Customer	01B86A	0.2 Hours
Replace Suspect HEC Module (Includes Inspection)	01B86B	0.9 Hour
Special Handling:	Misc. Expense Code "LCHP"	See Special Handling

PARTS REQUIREMENTS

Parts Ordering Information

Parts will not be direct shipped for this program. Order your parts requirement by contacting one of the Instrument Cluster Products Toll-Free Numbers listed below. When calling be sure to have Warranty Repair Form FCS 1878 filled out with information pertaining to the vehicle being serviced.

U.S. MPH/KPH 800-259-9700

Canada KPH/MPH 888-355-9098

Part Number	Description	Quantity
1W1Z-10849-AB	Hybrid Electronic Cluster MPH (English)	1
1W1Z-10849-BB	Hybrid Electronic Cluster KPH (Metric)	1

DEALER PRICE

For latest prices, check or call your:

- DOES II
- Updated Price Book

EXCESS STOCK RETURN

Excess stock returned for credit must have been purchased from Ford Customer Service Division in accordance with Policy Procedure Bulletin 4000.