TRIM—INTERIOR DOOR PANEL CARPET INSERTS PEELING OFF OR LOOSE—VEHICLES BUILT BEFORE 6/10/2002	Article No. 02-15-4

FORD: 2003 CROWN VICTORIA

MERCURY: 2003 GRAND MARQUIS

ISSUE

Some 2003 Crown Victoria/Grand Marquis/Marauder vehicles built before 6/10/2002 may exhibit poor adhesion and peeling of the door trim panel decorative carpet inserts. This may be aggravated by hot or humid conditions.

ACTION

Remove the door trim panel carpet inserts. Spray the door trim panel plastic surface with primer, allow to dry and re-affix the carpet in place with Motorcraft Trim and Weatherstrip Adhesive. Refer to the following Service Procedure for details.

SERVICE PROCEDURE

1. Remove the carpet from BOTH front doors.
2. Mask the door trim panels around the carpet attachment surface.
3. Spray the surface with primer (F6AZ-19A316-BA) and allow to flash dry. Follow the instructions provided with the can.
4. Repeat Step 3.
5. Using the applicator brush, apply Motorcraft Trim and Weatherstrip Adhesive (TA-14) to the carpet inserts and to the corresponding door trim panel surface. TA-14 is a black adhesive supplied in a metal can.

NOTE

DO NOT APPLY ADHESIVE WITHIN 1/4 INCH OF ANY EDGE AS IT MAY SQUEEZE OUT AND BECOME VISIBLE.

6. Allow adhesive to cure for five minutes.
7. Carefully position carpet to door panels and press in place.

NOTE

RE-POSITIONING OF THE CARPET INSERT IS DIFFICULT ONCE CONTACT IS MADE.

8. Inspect rear door carpet/repair if necessary.

PART NUMBER	PART NAME
F6AZ-19A316-BA TA-14	Primer Motorcraft Trim And Weatherstrip Adhesive

OTHER APPLICABLE ARTICLES: NONE

WARRANTY STATUS: Eligible Under The Provisions Of Bumper To Bumper Warranty Coverage

OPERATION	DESCRIPTION	TIME
021504A	Reinstall Carpet Insert On Interior Door Trim Panels: Both Front Doors	1.1 Hrs.
021504B	Reinstall Carpet Insert On Interior Door Trim Panels: Both Front Doors And One Rear Door	1.6 Hrs.
021504C	Reinstall Carpet Insert On Interior Door Trim Panels: Both Front Doors And Both Rear Door	2.0 Hrs.

DEALER CODING

BASIC PART NO.	CONDITION CODE
5423942	33

OASIS CODES: 107000

Copyright © 2002 Ford Motor Company