SUPPLEMENTAL CERTIFICATION LABEL

AFFECTED VEHICLES: CERTAIN 2000 MODEL YEAR TAURUS AND SABLE

SERVICE PROCEDURE

1. Open the driver door and clean the area below the certification label using the supplied alcohol wipe or isopropyl alcohol and a clean rag. Allow the area to dry.
2. Peel the backing off of the ***new*** supplemental certification label and install it as shown in the illustration below.



SUPPLEMENTAL SAFETY CERTIFICATION LABEL

00L03DA

FIGURE 1

CPR © 2000 FORD MOTOR COMPANY
DEARBORN, MICHIGAN 48121
09/00