Ford Motor Company

A. R. O'Neill
Director
Vehicle Service and Programs
Ford Customer Service Division

Ford Motor Company
P. O. Box 1904
Dearborn, Michigan 48121

October 2000

TO: All Ford and Lincoln Mercury Dealers

SUBJECT: Special Field Action 00L03 – Certain 2000 Model Year Taurus and Sable Vehicles - Supplemental Safety Certification Label

OASIS : No – Labels will be mailed directly to owners
OWNER LIST: No
PARTS RETURN: No
PROGRAM TERMS: This program will be in effect until March 31, 2001, regardless of mileage.

AFFECTED VEHICLES

Certain 2000 model year Taurus and Sable vehicles built at the Atlanta Assembly Plant from Job #1, 2000 through July 1, 2000 and built at the Chicago Assembly Plant from Job #1, 2000 through June 30, 2000.

NON-COMPLIANCE

In the affected vehicles, information on the vehicle maximum load (occupants plus luggage), number of occupants (occupants), and luggage load (luggage) is either missing or incorrectly stated on the safety certification label. The supplemental label will state the correct information for the customer.

SERVICE ACTION

A supplemental safety certification label that states the correct information will be mailed directly to owners of the affected Taurus and Sable vehicles. The owners will be given instructions to place the supplemental safety certification label on the door next to the existing label. However, if the owner chooses to have the label installed by a dealer, this service may be performed by service personnel.

ADDITIONAL CERTIFICATION LABELS

To assist customers who prefer to have this service completed at the dealership and arrive without the label, please call the Recall Hotline at 1-800-325-5621 to obtain copies of the label.

ATTACHMENTS

Attachment I: Administrative Information
Attachment II: Labor Allowances and Parts Ordering Information
Attachment III: Technical Information
Customer Notification Letter

QUESTIONS?

Claims Information:……..1-800-423-8851
Other Recall Questions:……..1-800-325-5621

Sincerely,



Ann O'Neill
Director
Vehicle Service and Programs

Special Field Action 00L03
2000 Model Year Taurus and Sable Vehicles
Supplemental Safety Certification Label

OASIS

OASIS will not be activated for this program.

PLEASE NOTE

Correct all vehicles in stock before delivery. Federal law requires dealers to complete any outstanding safety recall service before a new vehicle is delivered to the buyer or lessee. Violation of this requirement by a dealer could result in a civil penalty of up to $1,100 per vehicle.

DEALER-OWNER CONTACT

An owner list will not be provided.

CLAIMS PREPARATION AND SUBMISSION

- Enter claims using DWE.
- Refer to ACESII manual for claims preparation and submission information.

Special Field Action 00L03
2000 Model Year Taurus and Sable Vehicles
Supplemental Safety Certification Label

LABOR ALLOWANCES

Description	Labor Operation	Labor Time
Install label next to the existing label on the driver's door for customer, if requested	00L03B	0.2 Hrs.

PARTS REQUIREMENTS

Ordering Instructions for Additional Certification Labels

The supplemental safety certification labels (Part Number 1U5A-19G318-BA) for this program are being sent directly to customers of the affected vehicles. Additional labels may be ordered by calling the Recall Hotline at 1-800-325-5621. Inform the operator you are calling in regard to Special Field Action Program 00L03. Be prepared to provide your name, address, dealer P & A code, and how many labels you need.

DEALER PRICE

Dealers will not be charged for the supplemental safety certification labels ordered under this program.

Ford Motor Company

Ford Motor Company
P. O. Box 1904
Dearborn, Michigan 48121
1-800-392-3673
www.ownerconnection.com

October 2000

00L03

Mr. John Sample
123 Main Street
Anywhere, USA 12345

Your Vehicle Identification Number: 12345678901234567

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

Ford Motor Company has decided that certain 2000 Taurus or Sable vehicles fail to conform to the requirements specified in the Federal Motor Vehicle Safety Standard (FMVSS) No. 110 Tire Selection and Rims.

Information on the vehicle maximum load (occupants plus luggage), number of occupants (occupants), and luggage load (luggage) is either missing or incorrectly stated on the safety certification label. Although this does not affect your vehicle's performance, we are required to provide you with the correct information. We apologize for this inconvenience and want to assure you that we are dedicated to correcting this condition. Our commitment, together with your dealer, is to provide you with the highest level of service and support possible.

What the non-compliance issue is…	A safety certification label with incomplete information may have been unintentionally installed on your 2000 model year Taurus or Sable. This incomplete label does not indicate the appropriate maximum load, occupant number, and luggage load information.
What *Ford Motor Company* and your dealer will do…	**Enclosed is a supplemental label to place next to the existing safety certification label. This label has the appropriate load information. The supplemental certification label is provided free of charge.** To install the label yourself, instructions are enclosed. If you prefer, your dealer will install the safety certification label for you at no cost.
If you've changed address or sold the vehicle…	Please fill out the enclosed prepaid postcard and mail it to us if you have changed address or sold the vehicle.

If you have concerns…

If you have trouble getting your vehicle repaired promptly without charge, please contact the Ford Motor Company North American Customer Assistance Center and one of our representatives will be happy to assist you:

CALL: (800) 392-3673
(800) 232-5952 (TDD for the Hearing Impaired)

Office Hours: 8am - 11pm (Monday-Friday) ET
9am - 6pm (Saturday) ET

or you may contact us through the Internet at:
www.ownerconnection.com

Our current response time to Internet inquiries is three business days.

You also may send a complaint to the Administrator, National Highway Traffic Safety Administration, 400 Seventh Street, S. W., Washington, D. C. 20590 or call the toll free Auto Safety Hotline at 1-800-424-9393 (Washington, D. C. area residents may call 1-202-366-0123).

Quality Care service is there for you all year round.

QualityCare at your service

Quality Care is the commitment of Ford Motor Company and its dealerships to provide you with a superior service and ownership experience. While we regret the inconvenience caused by this notification, we stand committed with our Ford and Lincoln Mercury dealers to assist you with all of your automotive service needs. With our nationwide dealer network, we're here to ensure you receive Quality Care service so that your vehicle maintains peak performance throughout your ownership experience.

We pride ourselves on becoming the world's leading consumer company for automotive products and services. Thank you for your attention to this important matter.


Sincerely,



Ann O'Neill
Director
Vehicle Service and Programs

LABEL INSTALLATION

- Open the driver door.
- Clean the area below the certification label using the supplied alcohol wipe or isopropyl alcohol and a clean rag.
- Allow the area to dry completely.
- Peel the backing off of the ***new*** supplemental certification label and install it as shown in the illustration below.



SUPPLEMENTAL SAFETY CERTIFICATION LABEL

00L03CA

CPR © 2000 FORD MOTOR COMPANY
DEARBORN, MICHIGAN 48121
09/00