• **DRIVEABILITY—NO CRANK/NO START—MOISTURE FREEZES IN STARTER SOLENOID IN TEMPERATURES BELOW -12 DEGREES C (10 DEGREES F)** • **ELECTRICAL—NO CRANK/NO START—MOISTURE FREEZES IN STARTER SOLENOID IN TEMPERATURES BELOW -12 DEGREES C (10 DEGREES F)**	**Article No. 00-23-8**

FORD: 1997-2000 F-150, F-250 LD

ISSUE

Some vehicles may exhibit a no crank/no start condition in temperatures below -12°C (10°F). This may be caused by moisture in the starter solenoid resulting in frozen starter solenoid electrical contacts.

ACTION

To prevent the possibility of moisture entering the starter under the solenoid and contaminating the electrical contacts, replace the starter solenoid with a revised solenoid and gasket for improved sealing.

SERVICE PROCEDURE

NOTE

PERFORM ALL NORMAL ELECTRICAL DIAGNOSTICS BEFORE PROCEEDING WITH STARTER REMOVAL. REFER TO THE APPROPRIATE WORKSHOP MANUAL, SECTION 303-06, TO CHECK BATTERY AND ELECTRICAL CONNECTION CONDITION.

1. Remove starter from vehicle (refer to the Workshop Manual, Section 303-06).
2. Remove solenoid from starter by removing motor terminal shunt nut. Retain nut.
3. Completely loosen the two (2) attaching screws at the base of the solenoid. Screws are captured by motor housing.
4. Remove solenoid by sliding away from motor housing, then unhooking the solenoid rod from the motor lever.
5. Attach the revised Starter Solenoid (F8ZZ-11390-BA) which has a gasket included by reversing the steps above.
6. Hook the revised solenoid rod into the lever "fork," taking care that the solenoid terminal with silver connecting strap is closest to the motor housing.
7. Install solenoid screws and torque to 7.25 ±2.25 N•m (64 ±20 LB-IN).
8. Install motor terminal nut and torque to 12 ±3 N•m (106 ±25 LB-IN).
9. Reinstall starter into vehicle.

PART NUMBER	PART NAME
F8ZZ-11390-BA	Starter Solenoid

OTHER APPLICABLE ARTICLES: NONE

WARRANTY STATUS: Eligible Under The Provisions Of Bumper To Bumper Warranty Coverage

OPERATION	DESCRIPTION	TIME
002308A	Replace Starter Solenoid With Revised Solenoid And Gasket	0.7 Hr.

DEALER CODING

BASIC PART NO.	CONDITION CODE
11390	42

OASIS CODES: 203000, 203200, 601300, 603300

Copyright © 2000 Ford Motor Company