Ford Motor Company

A. R. O'Neill
Director
Vehicle Service and Programs
48121
Ford Customer Service Division

Ford Motor Company
P. O. Box 1904
Dearborn, Michigan

October 2001

TO: All Ford and Lincoln Mercury Dealers

SUBJECT: Special Field Action 01L05: Certain 2001 Model Year Focus ZX3 Vehicles With Midnight Black Interiors – Instrument Panel (I/P) Fuse Cover Replacement

OASIS: No, Instrument panel fuse covers will be mailed to owners/dealers.
OWNER LIST: No
PROGRAM TERMS: This program will be in effect until, April 30, 2002, regardless of mileage.

VEHICLES COVERED BY THIS ACTION

Certain 2001 Focus ZX3 vehicles built with Midnight Black interiors at Hermosillo Assembly Plant from August 29, 2001 through September 6, 2001.

REASON FOR PROGRAM

These vehicles were produced with 2002 model year I/P fuse covers instead of 2001 model year fuse covers. Fuse locations and capacity ratings marked on the inside of the covers differ between the two model years.

SERVICE ACTION

In-stock units:

Dealers will be mailed 2001 model year I/P fuse covers along with a VIN list and a copy of the owner letter for in-stock affected units.

Sold units:

Customers will be mailed 2001 model year I/P fuse covers and an installation sheet. Customers will be given the opportunity to install the cover themselves or have their local dealer install the cover for them.

© Copyright 2001 Ford Motor Company


ATTACHMENTS

Attachment I: Administrative Information
Attachment II: Labor Allowances and Parts Ordering Information
Attachment III: Technical Information
Customer Notification Letter

QUESTIONS?

Claims Information: ……..1-800-423-8851
Other (Dealer Only) Program Questions: ……1-800-325-5621

Sincerely,



Ann O'Neill
Director
Vehicle Service and Programs

© Copyright 2001 Ford Motor Company

Special Field Action 01L05
Certain 2001 Focus ZX3 Vehicles With Midnight Black Interiors
Instrument Panel Fuse Cover Replacement

OASIS

OASIS will not be activated for this program.

PLEASE NOTE

Correct all vehicles in stock before delivery.

DEALER-OWNER CONTACT

An owner list will not be provided. A VIN list for dealer in-stock units will be provided along with the fuse cover(s) mailed to the dealer.

CLAIMS PREPARATION AND SUBMISSION

- Enter claims using DWE.
- Refer to ACESII manual for claims preparation and submission information.

© Copyright 2001 Ford Motor Company

Special Field Action 01L05
Certain 2001 Focus ZX3 Vehicles Built With Midnight Black Interiors
Instrument Panel Fuse Cover Replacement

LABOR ALLOWANCES

Description	Labor Operation	Labor Time
Install I/P Fuse Cover on In-Stock Units or Upon Customer Request.	01L05B	0.2 Hours

PARTS REQUIREMENTS

In-stock unit:

Fuse covers for your in-stock units will be mailed to your dealership the beginning of November. Contained with the fuse covers will be a VIN list of affected in-stock units. To order additional covers contact the Special Service Support at 1-800-325-5621.

Sold Units:

The instrument panel fuse covers for this program are being mailed directly to owners of the affected vehicles. If a customer misplaces their fuse cover an additional fuse cover may be ordered by calling the Special Service Support Center at 1-800-325-5621.

Note: When charging fuse cover out on claim, refer to part package or current parts catalog for part number.

DEALER PRICE

For latest prices, check DOESII or updated price book.

EXCESS STOCK RETURN

Excess stock returned for credit must have been purchased from Ford Customer Service Division in accordance with Policy Procedure Bulletin 4000.

© Copyright 2001 Ford Motor Company

Ford Motor Company

A. R. O'Neill
Ford Motor Company
P. O. Box 1904
Dearborn, Michigan 48121

01L05 October 2001

Mr. John Sample
123 Main Street
Anywhere, USA 12345

Your Vehicle Identification Number: 12345678901234567

At Ford Motor Company our focus is on quality and customer satisfaction. To keep customers satisfied with our products we occasionally make product changes. Unfortunately a change occurred at the end of production for the 2001 model year which resulted in a 2002 model year part being installed on your 2001 model year Focus ZX3.

Ford Motor Company is replacing the instrument panel fuse cover on certain 2001 model year Focus ZX3 vehicles with Midnight Black interiors.

Reason For This Program…

Your 2001 model year Focus ZX3 was assembled with a 2002 model year instrument panel fuse cover. Fuse locations and capacity ratings on the inside of the covers are different between the two model years.

What *Ford Motor Company* and your dealer will do…

Enclosed is a 2001 model year instrument panel fuse cover and an installation instruction sheet to help you install the fuse cover correctly. Please refer to the instructions. If you prefer, your dealer will install the fuse cover for you at no cost.

What we are asking you to do…

Please install the enclosed instrument panel fuse cover or contact your dealer for a service date for Special Field Action 01L05.

On your appointment date bring this letter and the enclosed fuse cover to your dealer. If you lose your fuse cover let your dealer know when you request a service date, so another fuse cover can be ordered.

If you do not already have a servicing dealer, please access www.dealerconnection.com for dealer addresses, maps, and driving instructions.

© Copyright 2001 Ford Motor Company

If you've changed address or sold the vehicle...

Please fill out the enclosed prepaid postcard and mail it to us so we can update our records. If you have sold the vehicle, the information you provide on the postcard will be used to notify the new owner.

If you have questions…

If you have trouble getting your vehicle repaired promptly and without charge, please contact your dealership's Service Manager for assistance. If you still have concerns, please contact the Ford Motor Company Customer Relationship Center and one of our representatives will be happy to assist you:

Call (866) 436-7332

Office Hours (Eastern Time Zone)
Monday through Friday: 8AM – 11PM
Saturday: 8AM – 6PM

Hearing impaired call (800) 232-2952. TDD for the hearing impaired.

Or you may contact us through the Internet …

www.ownerconnection.com

Quality Care service is there for you all year round.

QualityCare™ at your service

Quality Care is the commitment of Ford Motor Company and its dealerships to provide you with a superior service and ownership experience. We stand committed with our Ford and Lincoln Mercury dealers to assist you with all of your automotive service needs. With our nationwide dealer network, we are here to ensure you receive Quality Care service so that your vehicle maintains peak performance throughout your ownership experience.

We pride ourselves on becoming the world's leading consumer company for automotive products and services. Thank you for your attention to this important matter.

Sincerely,



Ann O'Neill
Director
Vehicle Service and Programs

© Copyright 2001 Ford Motor Company

FOCUS INSTRUMENT PANEL FUSE COVER REPLACEMENT

1. Open the driver side door.
2. Remove the instrument panel fuse cover by grasping it at the bottom and then pulling it away from the instrument panel. Then discard the fuse panel cover. See Figure 1.




FIGURE 1

3. Install the ***new*** instrument panel fuse cover by inserting the two (2) tabs at the top into the openings in the instrument panel and then pushing the bottom toward the instrument panel.
4. Close the driver side door.

Ford Motor Company

CPR © 2001 FORD MOTOR COMPANY
DEARBORN, MICHIGAN 48121
10/01