NOISE—“MOANING/DRONING” DURING LIGHT ACCELERATION AT HIGHWAY SPEEDS	Article No. 01-21-7

LINCOLN: 2000-2002 LS

This article is being republished in its entirety to update the Model Year coverage and to update the parts required.

ISSUE

Some vehicles may exhibit a “moaning/droning” noise during light accelerations with the transmission in 5th gear at highway speeds (100-130 km/h (60-65 mph) for V6 vehicles or 80-90 km/h (50-55 mph) for V8 vehicles). This noise will disappear if the transmission is shifted to 4th gear or when lifting the throttle. The noise may be due to the body reacting to a resonant frequency generated by the powertrain.

ACTION

Install revised larger diameter rear halfshafts (1W6Z-4K138-AA (RH) and 1W6Z-4K139-AA (LH). The larger diameter halfshafts should reduce the resonant frequencies generated by the powertrain. Refer to the 2000-2002 LS Workshop Manual, Section 205-05 for installation procedure.

PART NUMBER	PART NAME
1W6Z-4K138-AA	Halfshaft - RH
1W6Z-4K139-AA	Halfshaft - LH

OTHER APPLICABLE ARTICLES: NONE
SUPERSEDES: 00-10-5
WARRANTY STATUS: Eligible Under The Provisions Of Bumper To Bumper Warranty Coverage

OPERATION	DESCRIPTION	TIME
012107A	Replace Halfshafts	1.5 Hrs.

DEALER CODING

BASIC PART NO.	CONDITION CODE
4K138, 4K139	42

OASIS CODES: 403000, 497000, 509000, 597997, 702000, 702200, 702300, 703000, 703200, 703300

Copyright © 2001 Ford Motor Company