Related Newsletter Articles

97M91 and 01M02 Parts Update Effective February 2002

03/04/2002

A parts update letter has been issued to replace the December 2001 parts update. This update includes differences in intake manifolds based on the specific alternator used on 1998 - 2000 Model Year Crown Victoria, Grand Marquis and Lincoln Town Cars. This update does not affect intake manifold applications for Thunderbird, Cougar and Mustang.
NOTE: The intake manifolds specified in the subject programs have been obsoleted. Please consult the chart below to determine part requirements.

For Crown Victoria, Grand Marquis & Town Car Applications:
The alternator installed on a particular vehicle determines which intake manifold is to be installed. Certain applications use a high output alternator on 1998 - 2000 Model Year Crown Vic, Grand Marquis & Town Cars and are identified by the engineering number located on the alternator case.

- All 1998 Models (Police/Limo/Retail) have a 6G alternator
- 1999-2000 Crown Victoria, Grand Marquis, Town Car - Police/Limo packages have a 6G alternator
- 1999-2000 Crown Victoria, Grand Marquis, Town Car - Retail models, could have either a 4G or 6G alternator

See chart attached below:

MODEL YEAR	MODELS	OLD INTAKE MANIFOLD PART#	NEW INTAKE MANIFOLD**
1996 - 1997 1996 - 1998	Thunderbird, Cougar Mustang	F8AZ-9424-BC*	F6SZ-9424-AA
1999 - 2001	Mustang	1L2Z-9424-DA*	1R3Z-9424-AAA
1996 - 1997	Crown Victoria, Grand Marquis, Town Car - *All*	F8AZ-9424-BC*	F8AZ-9424-CA
1998	Crown Victoria, Grand Marquis, Town Car: - *All Vehicles*	F8AZ-9424-BC*	F8AZ-9424-CA
1999 - 2000	Crown Victoria, Grand Marquis, Town Car: **Police/Limo package:** *6G ALTERNATOR-ID F8AU-10300-AC* **Retail Vehicles:** *4G ALTERNATOR-ID XW7Z-10300-AC* *6G ALTERNATOR-ID F8AU-10300-AC*	 F8AZ-9424-BC* F8AZ-9424-BC* F8AZ-9424-BC*	 F8AZ-9424-CA^ F8AZ-9424-BAA F8AZ-9424-CA
2001	Crown Victoria, Grand Marquis, Town Car: *Police, Limousine Vehicles*	1L2Z-9424-DA*	1W7Z-9424-BA
2001	Crown Victoria, Grand Marquis, Town Car: *Retail Vehicles*	1L2Z-9424-DA*	1W7Z-9424-AAA

***** Indicates the Obsolete Intake Manifold - DO NOT ORDER

^ For Police package vehicles only:
1998 - 2000 Police units that use manifold kit F8AZ-9424-CA, will also require a blue silicone upper radiator hose
P/N # 1W7Z-8260-AA

****** The new manifold does not have raised dowel pins where the 8592 thermostat housing mounts. The dowels are no longer required.

97M91 and 01M02 Parts Update

12/10/2001

Program 01M02: Additional Coverage on Certain 4.6L SOHC Intake Manifolds Installed on certain 1996-2001 Crown Victoria Taxis, Police cars and Lincoln Town Car Limousine and Livery cars

Program 97M91: Certain 1996-1998 Crown Victoria Taxis, Town Car Limo Prep & Livery Packages, 1996-1997 Thunderbird, Cougar and Mustang Vehicles Equipped With 4.6L SOHC Engines- Intake Manifold Additional Coverage

The intake manifolds specified in the subject programs have been obsoleted. Please consult the chart below to determine part requirements.

MODEL YEAR	MODELS	OLD INTAKE MANIFOLD PART#	NEW INTAKE MANIFOLD
1996 - 1997 1996 - 1998	Thunderbird, Cougar Mustang	F8AZ-9424-BC*****	F6SZ-9424-AA
1999 - 2001	Mustang	1L2Z-9424-DA*****	1R3Z-9424-AAA
1996 - 1997	Crown Victoria, Grand Marquis, Town Car - *All*	F8AZ-9424-BC*****	F8AZ-9424-CA
1998 - 2000	Crown Victoria, Grand Marquis, Town Car: *Police, Limousine Vehicles*	F8AZ-9424-BC*****	F8AZ-9424-CA
1998 - 2000	Crown Victoria, Grand Marquis, Town Car: *Retail Vehicles*	F8AZ-9424-BC*****	F8AZ-9424-BAA
2001	Crown Victoria, Grand Marquis, Town Car: *Police, Limousine Vehicles*	1L2Z-9424-DA*****	1W7Z-9424-BA
2001	Crown Victoria, Grand Marquis, Town Car: *Retail Vehicles*	1L2Z-9424-DA*****	1W7Z-9424-AAA

*****Indicates the Obsolete Intake Manifold - DO NOT ORDER

Copyright © 2001 Ford Motor Company
Published By: **Recall/Service Programs Department**
Ford Customer Service Division