Ford Motor Company

A. R. O'Neill
Director
Vehicle Service and Programs
48121
Ford Customer Service Division

Ford Motor Company
P. O. Box 1904
Dearborn, Michigan

August 2001

TO: All Ford and Lincoln Mercury Dealers

SUBJECT: Special Field Action 01L03: Certain 2001 Econoline E350 Cutaway vehicles built at Lorain Assembly Plant – with 11,500 GVWR

OASIS: No, Labels will be sent to Owners.
OWNER LIST: No
PROGRAM TERMS: This program will be in effect until February 28, 2002

VEHICLES COVERED BY THIS ACTION

Certain 2001 Econoline E350 Cutaway vehicles built with 11,500 GVWR at the Lorain Assembly Plant from August 7, 2000 through October 17th, 2000.

REASON FOR PROGRAM

These vehicles were produced with Door Post Certification Labels that state incorrectly the rear GAWR (Gross Axle Weight Rating) is 8350lbs. The correct rear GAWR information should be 7800lbs.

SERVICE ACTION

Customers will be sent the correct rear GAWR overlay label and an installation sheet. Customers will be informed that if they want a Dealer to install the overlay, they should contact their local Dealer.

ATTACHMENTS

Attachment I: Administrative Information
Attachment II: Labor Allowances and Parts Ordering Information
Attachment III: Technical Information
Customer Notification Letter(s)

QUESTIONS?

Claims Information: ……..1-800-423-8851
Other (Dealer Only) Program Questions: ……1-800-325-5621

Sincerely,

Ann O'Neill
Director
Vehicle Service and Programs

Special Field Action 01L03
Certain 2001 Econoline E350 Cutaway vehicles built with 11,500 GVWR
Incorrect Rear GAWR Information

OASIS

OASIS will not be activated for this program.

CLAIMS PREPARATION AND SUBMISSION

- Enter claims using DWE.
- Refer to ACESII manual for claims preparation and submission information.

RENTAL CARS

Rental vehicles are not approved for this program.

Special Field Action 01L03
Certain 2001 Econoline E350 Cutaway vehicles built with 11,500 GVWR
Incorrect Rear GAWR Information

LABOR ALLOWANCES

Description	Labor Operation	Labor Time
Install overlay label	01L03B	0.2 Hours

PARTS REQUIREMENTS

Ordering Instructions for additional labels.

The labels for this program are being sent directly to owners of the affected vehicles. Additional labels may be ordered by calling the Recall Hotline at 1-800-325-5621. Inform the operator you are calling in regard to Special Field Action 01L03.

DEALER PRICE

Dealers will not be charged for the labels ordered under this program.

Ford Motor Company

A. R. O'Neill
Ford Motor Company
P. O. Box 1904
Dearborn, Michigan 48121

01L03 August 2001

Mr. John Sample
123 Main Street
Anywhere, USA 12345

Your Vehicle Identification Number: 12345678901234567

Ford Motor Company is correcting the rear GAWR (Gross Axle Weight Rating) information stated on the driver side Door Post Certification Label in certain 2001 Econoline E350 Cutaway with 11,500 GVWR.

Reason For This Program…

The rear GAWR information on the Door Post Certification Label is incorrect. The rear GAWR information should read 7800lbs not 8350lbs as stated.

What *Ford Motor Company* and your dealer will do…

Ford Motor is sending the corrected overlay label and an installation instruction sheet to help you install the overlay correctly. If you would rather have a Dealer install the overlay label, please contact your local Dealer to make an appointment.

What we are asking you to do…

Install the enclosed overlay label or contact your dealer for a service date. Your dealer will install the overlay label at no charge to you. Please keep this letter as a reminder.

When you bring your vehicle in, show the dealer this letter. If you misplace this letter, your dealer will still do the work, free of charge.

If you do not already have a servicing dealer, please access www.dealerconnection.com for dealer addresses, maps, and driving instructions.

If you have changed address or sold the vehicle…

Please fill out the enclosed prepaid postcard and mail it to us so we can update our records. If you have sold the vehicle, the information you provide on the postcard will be used to notify the new owner.

If you have questions…

If you have trouble getting your vehicle repaired promptly and without charge, please contact your dealership's Service Manager for assistance. If you still have concerns, please contact the Ford Motor Company Customer Relationship Center and one of our representatives will be happy to assist you:

Call (866) 436-7332

Office Hours (Eastern Time Zone)
Monday through Friday: 8AM – 11PM
Saturday: 9AM – 6PM

Hearing impaired call (800) 232-2952. TDD for the hearing impaired.


Quality Care service is there for you all year round.

QualityCare™ at your service

Quality Care is the commitment of Ford Motor Company and its dealerships to provide you with a superior service and ownership experience. We stand committed with our Ford and Lincoln Mercury dealers to assist you with all of your automotive service needs. With our nationwide dealer network, we are here to ensure you receive Quality Care service so that your vehicle maintains peak performance throughout your ownership experience.

We pride ourselves on becoming the world's leading consumer company for automotive products and services. Thank you for your attention to this important matter.

Sincerely,



Ann O'Neill
Director
Vehicle Service and Programs

MODIFIED CERTIFICATION LABEL INSTALLATION

AFFECTED VEHICLES: CERTAIN 2001 MODEL YEAR E-SERIES CUTAWAY MODELS

1. Locate and wipe clean the original certification label on the driver's door B-pillar above the striker.
2. NOTE: To help properly align the ***new*** label over the original, the ***new*** label is the same dimension as the original and is clear except for the upper right corner which contains the revised information. Line up the outside edges and be sure the revised information covers only the words "BY FORD MOTOR COMPANY", and the GVWR and REAR GAWR ratings.

   Peel the backing from the ***new*** label and very carefully position and apply the ***new*** label over the original label. See Figure 1.




FIGURE 1

Ford Motor Company

CPR © 2001 FORD MOTOR COMPANY

DEARBORN, MICHIGAN 48121
08/01