Ford Motor Company

A. R. O'Neill
Director
Vehicle Service and Programs
48121
Ford Customer Service Division

Ford Motor Company
P. O. Box 1904
Dearborn, Michigan

May 2002

TO: All Ford and Lincoln Mercury Dealers

SUBJECT: DEMONSTRATION / DELIVERY HOLD: Emissions Recall 02E20: Certain 2002 Model Year 5.4 and 6.8L F-Super Duty, Excursion and E-Series Vehicles **-** Powertrain Control Module Reprogramming

AFFECTED VEHICLES

Vehicles Lines	Model Year	Assembly Plant	Build Dates
F-250/350/450/550 and Excursion	2002	Kentucky Truck Plant	Job #1 through March 14, 2002
F-250/350/450/550	2002	Cuautitlan Stamping & Assembly Plant	Job #1 through December 19, 2001
E-Series	2002	Lorain Assembly Plant	Job #1 through March 15, 2002

REASON FOR THIS RECALL

In some of the affected vehicles, the Powertrain Control Module (PCM) may contain software that does not comply with California On-Board Diagnostics regulations. Vehicles operating with this PCM software will not set required diagnostic trouble codes when rich or lean air/fuel mixture thresholds are exceeded.

SERVICE ACTION

Before demonstrating or delivering any of the vehicles involved in this recall, the dealer must inspect the calibration level of all of the affected vehicles. Reprogram the PCM in each vehicle that does not have the latest calibration installed (see "2002 MY PCM Reprogram Charts" in Attachment III). This must be done on all of the affected vehicles in your inventory as well as vehicles that have been delivered to customers.

NOTE: The State of California requires the completion of emission recall repairs prior to vehicle registration renewal. For vehicles registered in California, please provide the owner with a Vehicle Emission Recall Proof of Correction certificate after the repair has been performed. (These certificates may be obtained by contacting your regional office).

PLEASE NOTE

Correct all vehicles in stock before delivery. Under certain conditions, the malfunction indicator light will not illuminate as required in vehicles with this software. Vehicles with this software delivered to customers are being recalled. Sale of uncorrected vehicles to customers could lead to penalties under the Clean Air Act.

© Copyright 2002 Ford Motor Company

ATTACHMENTS

Attachment I: Administrative Information
Attachment II: Labor Allowances and Parts Ordering Information
Attachment III: Technical Information
Customer Letter (s)

QUESTIONS?

Claims Information: ……1-800-423-8851
Other Recall (Dealers Only) Questions: ……1-800-325-5621
Online Involved Unit Listings Questions:……1-800-555-9601

Sincerely,

Ann O'Neill
Director
Vehicle Service and Programs

© Copyright 2002 Ford Motor Company

DEMONSTRATION / DELIVERY HOLD: EMISSIONS RECALL 02E20
Certain 2002 Model Year 5.4 and 6.8L F-Super Duty, Excursion and E-Series Vehicles
Powertrain Control Module Reprogramming

OASIS

You must use OASIS to determine if a vehicle is eligible for this recall.

PROMPTLY CORRECT

Promptly correct all affected vehicles on your dealer Online Involved Unit Listing available on QCDealer.com. Also, correct other affected vehicles identified in OASIS which are brought to your dealership.

DEALER-OWNER CONTACT

Immediately contact any affected owner whose name is not on the list but identified in OASIS. Give the owner a copy of the Owner Letter and schedule a service date.

NOTE: These dealer listings may contain customer names and addresses obtained from Motor Vehicle Registration Records. The use of such motor vehicle registration data for any purpose other than in connection with this recall is a violation of law in several states/provinces/countries. Accordingly, you must limit the use of this listing to the follow-up necessary to complete this action.

REGIONAL CONTACT

Advise regional office if an owner:

- cannot be contacted.
- does not make a service date.

CLAIMS PREPARATION AND SUBMISSION

- Enter claims using DWE.
- Refer to ACESII manual for claims preparation and submission information.

RENTAL CARS

The use of rental vehicles is not authorized for this program.

© Copyright 2002 Ford Motor Company

DEMONSTRATION / DELIVERY HOLD: EMISSIONS RECALL 02E20
Certain 2002 Model Year 5.4 and 6.8L F-Super Duty, Excursion and E-Series Vehicles
Powertrain Control Module Reprogramming

LABOR ALLOWANCES

Description	Labor Operation	Labor Time
Inspect Calibration (PCM at Latest Level No Reflash Needed)	02E20A	0.3 Hours
Inspect and Reprogram PCM to Latest Level Calibration	02E20B	0.4 Hours
Administrative Allowance	Misc. Expense Code "ADMIN"	0.1 Hour

PARTS REQUIREMENTS / ORDERING INFORMATION

All Order Types Effective immediately Normal order process

Part Number	Description	Quantity
FPS-8262	Authorized Modifications Label	*1

***** Label orders come in packages of 25.

DEALER PRICE

Not applicable.

PARTS RETENTION

Not applicable.

EXCESS STOCK RETURN

Not applicable.

© Copyright 2002 Ford Motor Company