Ford Motor Company

February 2001

TO: Affected Ford and Lincoln Mercury Dealers

SUBJECT: Safety Recall 01S04: Certain 2000 Model Year Contour and Mystique Vehicles – Incorrect Brake Booster and Master Cylinder Assembly

AFFECTED VEHICLES

Certain 2000 model year Contour and Mystique vehicles built at the Cuautitlan Assembly Plant from October 30, 2000 through October 31, 2000.

SAFETY CONCERN

The subject vehicles (less than 80 units) were built with power brake boosters and master cylinder assemblies not intended to be installed in Contour or Mystique vehicles. The performance of the brake system, as built, meets all performance requirements. However, if only the power brake booster or the master cylinder is replaced with the correct Contour part during vehicle service, brake system performance will be reduced.

SERVICE ACTION

Dealers must replace the brake booster and master cylinder assembly on all the affected vehicles.

ATTACHMENTS

Attachment I:	Administrative Information
Attachment II:	Labor Allowances and Parts Ordering Information
Attachment III:	Technical Information
	Customer Letter

QUESTIONS?

Claims Information:……..……....1-800-423-8851
Other (Dealer Only) Recall Questions:……..……...1-800-325-5621

Sincerely,

Ann O'Neill
Director
Vehicle Service and Programs

© Copyright 2001 Ford Motor Company

Safety Recall 01S04
Certain 2000 model year Contour and Mystique vehicles
Incorrect Brake Booster and Master Cylinder Assembly

OASIS

You must use OASIS to determine if a vehicle is eligible for this recall.

CLAIMS PREPARATION AND SUBMISSION

- Enter claims using DWE.
- Refer to ACESII manual for claims preparation and submission information.

OWNER REFUNDS

Ford Motor Company will only refund owner-paid repairs made before the date of the Owner Letter (or after the date of the Owner Letter if an emergency repair was made away from the servicing dealer). Refer to ACESII manual for refund information.

RENTAL CARS

Rental vehicles are not approved for this program.

© Copyright 2001 Ford Motor Company

Safety Recall 01S04
Certain 2000 model year Contour and Mystique vehicles
Incorrect Brake Booster and Master Cylinder Assembly

LABOR ALLOWANCES

Description	Labor Operation	Labor Time
Replace Brake Booster and Master Cylinder Assembly	01S04B	1.7 Hours
Administrative Allowance	Misc. Expense Code "ADMIN"	0.1 Hour

PARTS REQUIREMENTS

Parts Ordering Information

Normal order process.

PLEASE NOTE: THERE ARE LESS THAN 80 VEHICLES INVOLVED IN THIS PROGRAM THAT WILL REQUIRE THE PARTS LISTED BELOW.

Part Number	Description	Quantity
F7RZ 2005 AA	Booster Assembly	1
F7RZ 2140 DA	Master Cylinder	1

ORDER INFORMATION

DOR/COR number **50267** identifies parts ordered for this program.

DEALER PRICE

For latest prices, refer to:

- DOES II
- Updated Price Book

EXCESS STOCK RETURN

Excess stock returned for credit must have been purchased from Ford Customer Service Division in accordance with Policy Procedure Bulletin 4000.

© Copyright 2001 Ford Motor Company

Safety Recall 01S04
Certain 2000 model year Contour and Mystique vehicles
Incorrect Brake Booster and Master Cylinder Assembly

Technical Instructions:

The procedure for replacing the vehicle's power brake booster and master cylinder assembly can be found in the 2000 Contour/Mystique WSM, section 206-07 "Power Brake Actuation". This section will also refer to 206-06 "Master Cylinder R&I", and section 206-00 "Brake System-General Information".

© Copyright 2001 Ford Motor Company

Ford Motor Company

A. R. O'Neill
Ford Motor Company
P. O. Box 1904
Dearborn, Michigan 48121

March 2002

Safety Recall 01S04

Mr. John Sample
123 Main Street
Anywhere, USA 12345

Your Vehicle Identification Number: 12345678901234567

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

Ford Motor Company has decided that a defect which relates to motor vehicle safety exists in certain 2000 model year Contour and Mystique vehicles. We apologize for this situation and want to assure you that, with your assistance, we will correct this condition. Our commitment, together with Ford and Lincoln Mercury dealers, is to provide you with the highest level of service and support possible.

What the issue is …

Some of the affected vehicles were built with power brake boosters and master cylinder assemblies not intended to be installed in Contour or Mystique vehicles. The performance of the brake system, as built, meets all performance requirements. However, if only the power brake booster or the master cylinder is replaced with the correct Contour or Mystique part during vehicle service, brake system performance will be reduced.

What Ford Motor Company and your dealer will do ...

Ford Motor Company will replace the brake booster and master cylinder assembly on your vehicle, free of charge (parts and labor).

How long will it take?

The time needed for this repair is less than one-half day. However, due to service scheduling requirements, your dealer may need your vehicle for a longer period of time.

What we are asking you to do …

Call your dealer without delay. If you do not already have a servicing dealer, please access www.dealerconnection.com for dealer addresses, maps, and driving instructions. Ask for a service date and whether parts are in stock for Safety Recall 01S04. If your dealer does not have the parts in stock, they can be ordered before scheduling your service date. Parts would be expected to arrive within a week after ordering.

© Copyright 2001 Ford Motor Company

When you bring your vehicle in, show the dealer this letter. However, if you misplace this letter, your dealer will still do the work, free of charge.

If you have already paid for this service …

If you paid to have this service done before the date of this letter, Ford is offering a refund. To receive the refund, please give your paid original receipt to your dealer. To avoid delays, do not send receipts to Ford Motor Company.

If you have changed address or sold the vehicle …

Please fill out the enclosed prepaid postcard and mail it to us so we can update our records. If you have sold the vehicle, the information you provide on the postcard will be used to notify the new owner about this safety recall.

If you have concerns …

If you have trouble getting your vehicle repaired promptly and without charge, please contact your dealership's Service Manager for assistance. If you still have concerns, please contact the Ford Motor Company Customer Relationship Center and one of our representatives will be happy to assist you:

Call (866) 436-7332

Office Hours (Eastern Time Zone)
Monday through Friday: 8AM – 11PM
Saturday: 8AM – 6PM

Hearing-impaired call (800) 232-5952 TDD for the hearing impaired.

Or you may contact us through the Internet …

www.ownerconnection.com

If you are still having trouble getting your vehicle repaired and without charge, you may write the Administrator, National Highway Traffic Safety Administration, 400 Seventh Street S. W., Washington, D. C. 20590 or call the toll free Auto Safety Hotline at 1-888-327-4236 or 1-800-424-9393.

Quality Care service is there for you all year long.



Quality Care is the commitment of Ford Motor Company and its dealerships to provide you with a superior service and ownership experience. While we regret the inconvenience caused by this program, we stand committed with our dealers to assist you with all of your automotive service needs. With our nationwide dealer network, we're here to ensure you receive Quality Care service so that your vehicle maintains peak performance throughout your ownership experience.

We pride ourselves on becoming the world's leading consumer company providing automotive products and services. Thank you for your attention to this important matter.

Sincerely,



Ann O'Neill
Director
Vehicle Service and Programs

© Copyright 2001 Ford Motor Company