Ford Motor Company

February 2001

TO: All Ford Medium Truck Dealers

SUBJECT: **Safety Recall 00S28**: Certain 2000 and 2001 Model Year F-650 and F-750 vehicles equipped with Air Brakes – Anti-Lock Brake ECU (Controller) Replacement

REF: Dealer Announcement dated May 10, 1999, Low Volume Recalls and Owner Notification Programs (Attachment IV)

AFFECTED VEHICLES

- Certain 2000 model year F-650 and F-750 vehicles equipped with air brakes and built at the Cuautitlan Assembly Plant from November 23, 1998 through August 17, 2000.
- Certain 2001 model year F-650 and F-750 vehicles equipped with air brakes and built at the Cuautitlan Assembly Plant from June 7, 2000 through August 29, 2000.

SAFETY CONCERN

In some of the affected vehicles the anti-lock brake ECU (Controller) may interpret wheel speed sensor background noise as actual wheel speed information. This may allow false activation of the anti-lock brake system at speeds below 20 mph when the brakes are applied.

SERVICE ACTION

To prevent the possibility of false activation of the anti-lock brake system, the dealership will replace the affected anti-lock brake ECU (Controller) with a revised ECU that has improved signal processing capability.

PLEASE NOTE

Correct all vehicles in stock before delivery. Federal law requires dealers to complete any outstanding safety recall service before a new vehicle is delivered to the buyer or lessee. Violation of this requirement by a dealer could result in a civil penalty of up to $5,000 per vehicle.

LOW VOLUME RECALL

This recall is being processed as a Low Volume Recall. This type of field action was announced in an All-Dealer letter dated May 10, 1999. (See Attachment IV)

Owners will be contacting the Low Volume Recall Coordination Center to arrange for this service. We will advise you via MORS III of the owners that chose your dealership to perform the service provided by this Recall program. The parts will be ordered for you by the Program Coordination Center.

You are requested to contact the owner and arrange for this service. (Note that our Coordination Center will advise owners that they will hear from you within the next two business days.)


ATTACHMENTS

Attachment I: Administrative Information
Attachment II: Labor Allowances and Parts Ordering Information
Attachment III: Technical Information
Attachment IV: Low Volume Dealer Announcement Letter
Customer Notification Letter

QUESTIONS?

Claims Information:……..……....1-800-423-8851
Other (Dealer Only) Recall Questions:…….……...1-800-325-5621

Sincerely,



Ann O'Neill
Director
Vehicle Service and Programs

Safety Recall 00S28:
Certain 2000 and 2001 Model Year F-650 and F-750 vehicles equipped with Air Brakes – Anti-Lock Brake ECU (Controller) Replacement

OASIS

You must use OASIS to determine if a vehicle is eligible for this recall.

PROMPTLY CORRECT

Promptly correct all affected vehicles on your dealer Recall/ONP Involved Unit Listings available on QCDealer.Com or in the Ford Dealer Consolidated Communicator (FDCC). Also, correct other eligible vehicles, which are brought to your dealership.

You must contact the Low Volume Recall Coordination Center at 1-800-248-0186 to arrange for parts if you have an involved vehicle in stock. When calling this number, identify Safety Recall 00S28 and have the VIN of the dealer stock vehicle to be serviced.

DEALER-OWNER CONTACT

When you receive notification through MORS III, you should contact the owner and arrange for this service. Please note that our Coordination Center will advise owners that they will hear from you within the next two business days. For more information, see referenced copy of "Low Volume Announcement Letter" dated May 10,1999.

Immediately contact any of your affected owners whose names are not on your VIN list but identified in OASIS. Give the owner a copy of the Owner Letter and schedule a service date.

REGIONAL CONTACT

Advise regional office if an owner:

- cannot be contacted.
- does not make a service date.

CLAIMS PREPARATION AND SUBMISSION

- Enter claims using DWE.
- Refer to ACESII manual for claims preparation and submission information.

OWNER REFUNDS

Ford Motor Company will only refund owner-paid repairs made before the date of the Owner Letter (or after the date of the Owner Letter if an emergency repair was made away from the servicing dealer). Refer to ACESII manual for refund information.

RENTAL CARS

Rental vehicles are not approved for this program.

Safety Recall 00S28:
Certain 2000 and 2001 Model Year F-650 and F-750 vehicles equipped with Air Brakes – Anti-Lock Brake ECU (Controller) Replacement

LABOR ALLOWANCES

Description	Labor Operation	Labor Time
Replace Anti-Lock Brake ECU (Controller)	00S28B	0.6 Hour
Administrative Allowance	Misc. Expense Code "ADMIN"	0.1 Hour

PARTS REQUIREMENTS

Parts Ordering Information

Parts will not be direct shipped for this campaign. This is a "Small Volume" program and dealers/customers will be required to call the Campaign Headquarters at 1-800-248-0186 and supply the VIN of the vehicles to order parts. This process will remain in effect for 90 days after the launch of the campaign.

All order types	90 days after launch	Call 1-800-248-1086
All order types	91 days after launch	Normal order process

Part Number	Description	Quantity
YC3Z-2C219-AC	ECU (controller)	1

ORDER INFORMATION

DOR/COR number 50221 identifies parts ordered for this campaign.

DEALER PRICE

For latest prices, refer to DOES II or updated price book.

EXCESS STOCK RETURN

Excess stock returned for credit must have been purchased from Ford Customer Service Division in accordance with Policy Procedure Bulletin 4000.

ATTACHMENT IV

All Dealer Letter

Part Procurement Process for Low Volume Programs

Ford Customer Service Division



Ford Motor Company
P.O. Box 1904
Dearborn, Michigan 48121

May 10, 1999

To: All Ford and Lincoln Mercury Dealers

cc: All Parts Managers
All Service Managers

Subject: Updated Part Procurement Process For Low Volume Recalls

The purpose of this communication is to update the process for dealer acquisition of service parts for certain Recalls/Owner Notification Programs with a small number of involved vehicles.

Background:

- Situations where Recalls/Owner Notification Programs have a small number of involved units require special handling.
- There are no controls in the parts system to prevent the over-ordering of parts in low volume situations.
- Many dealers order one or more parts even if they do not have an involved unit to insure customer satisfaction. This can result in parts in the inventory of dealers who do not need them and exhausted supply for dealers who do need them.
- With existing procedures, there is a cost to the Company and the Dealers (handling, returning, scrapping, etc.).

What's "Small Volume"?

- Generally, recalls, or ONP's involving 5,000 or fewer vehicles.

What We Propose

- Procedure to better manage "Parts-To-Affected-Vehicle" process.
- Vehicle owner (retail customer/fleet/dealer) requested to contact a "process facilitator" via a special 1-800 toll-free line or with a special postcard provided with the owner letter.
- Process facilitator verifies VIN/Owner information and works with owner (or dealer) to identify repairing dealer.
- Process facilitator inputs part order and sends a MORS III message with Customer/VIN/part shipping information to the identified repairing dealer.
- Dealer would be charged for the part at the lowest acquisition cost.

What's Different:

- Owner asked to call special toll-free line or send back special postcard.
- Parts would not be available through the normal parts ordering system.
- Owners would need to have an appointment.

Dealer Benefits:

- Eliminates back-orders—guarantees part availability.
- Increases customer satisfaction with your "Service Experience"
- New process will enable dealers to initiate pro-active service scheduling—with the information we will provide on the MORS III message, you call the customers to arrange a service appointment knowing that the part will be there and the customer's vehicle needs service.

Additional details will be provided as specific Recalls/Owner Notification Programs suitable for this process are launched.

We ask that you share this procedure with your parts and service personnel to insure they are aware of this process.

Ann O'Neill
Director
Vehicle Service and Programs

R. E. Turecki
Director
Global Parts Supply and Logistics

Ford Motor Company

Ford Motor Company
P. O. Box 1904
Dearborn, Michigan 48121

March 2001

00S28

Mr. John Sample
123 Main Street
Anywhere, USA 12345

Your Vehicle Identification Number: 12345678901234567

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

Ford Motor Company has decided that a defect which relates to motor vehicle safety exists in certain 2000 and 2001 model year F-650 and F-750 vehicles.

We apologize for this situation and want to assure you that with your assistance we will correct this condition. Our commitment, together with Ford and Lincoln Mercury dealers, is to provide you with the highest level of service and support possible.

What the safety issue is …	During application of service brakes, if vehicle speed is below 20 mph, the anti-lock brake ECU (Controller) in your vehicle may allow inappropriate activation of the anti-lock brakes resulting in increased stopping distance.
What Ford Motor Company and your dealer will do ...	Ford Motor Company will repair your vehicle free of charge (parts and labor.) To restore proper anti-lock brake operation, your dealer will replace the anti-lock brake ECU (Controller) with a redesigned ECU.
How long will it take?	The time needed for this repair is less than one-half day. However, due to service scheduling issues, your dealer may need your vehicle for a longer period of time.

What we are asking you to do …	Call toll-free 1-800-248-0186 and inform the Ford representative that you wish to have your vehicle serviced under Safety Recall 00S28. Representatives are available 7:30AM to 7:30PM Monday through Friday, and 8:00AM to 3:00PM on Saturday (times are Eastern Time). Please have this letter with you when you call. The Ford representative will ask for the serial number of your vehicle. The serial number is printed on the top of this letter. Arrangements will be made with the dealership of your choice to have parts available. The dealership will call you to schedule an appointment. If you have not heard from your dealer within two working days, call your dealer to request a service appointment. You need do nothing else except bring your vehicle to the dealership on the service date. If you misplace this letter, your dealer will still do the work, free of charge.
If you've already paid for this service …	If you paid to have this service done before the date of this letter, Ford is offering a full refund. For the refund, please give your paid original receipt to your dealer. To avoid delays, do not send receipts to Ford Motor Company.
If you've changed address or sold the vehicle …	Please fill out the enclosed prepaid postcard and mail it to us if you have changed address or sold the vehicle.

If you have concerns …

If you have trouble getting your vehicle repaired promptly and without charge, please contact your dealership's Service Manager. If you still need assistance, please contact the Ford Motor Company Customer Relationship Center and one of our representatives will be happy to assist you:

CALL: (800) 392-3673
(800) 232-5952 (TDD for the Hearing Impaired)

Office Hours: (Eastern Standard Time)

Monday-Friday: 8am - 11pm
Saturday: 9am - 6pm

or you may contact us through the Internet at:
www.ownerconnection.com
Our current response time to Internet inquiries is three business days.

You also may send a complaint to the Administrator, National Highway Traffic Safety Administration, 400 Seventh Street S. W., Washington, D. C. 20590 or call the toll free Auto Safety Hotline at 1-888-327-4236 or 1-800-424-9393.


Quality Care service is there for you all year round.

QualityCare™ at your service

Quality Care is the commitment of Ford Motor Company and its dealerships to provide you with a superior service and ownership experience. While we regret the inconvenience caused by this program, we stand committed with our dealers to assist you with all of your automotive service needs. With our nationwide dealer network, we're here to ensure you receive Quality Care service so that your vehicle maintains peak performance throughout your ownership experience.

We pride ourselves on becoming the world's leading consumer company for automotive products and services. Thank you for your attention to this important matter.

Sincerely,



Ann O'Neill
Director
Vehicle Service and Programs