TRANSMISSION—4R100—SERVICE PROCEDURE FOR ORANGE SERVICE TAGGED TRANSMISSION	Article No. 99-21-11

FORD: 2000 ECONOLINE, EXCURSION, EXPEDITION, F-150, F-250, SUPER DUTY F SERIES

LINCOLN: 2000 NAVIGATOR

ISSUE

Selected transmissions have an orange "PRIOR TO REPAIR" tag (Figure 1) on the transmission fluid pan. The orange tag refers to this TSB which includes specific instructions to be followed prior to replacement and/or repair and provides a toll-free number to be called by all U.S. and Canadian dealers (not applicable outside the U.S. and Canada).

ACTION

Prior to December 31, 2000, do not disassemble or repair these orange tagged 4R100 transmissions. Perform the following diagnostic steps, record your findings, and contact Ford Motor Company at 1-800-543-8742. Refer to the following Service Procedure for details.

SERVICE PROCEDURE

1. Check and record transaxle fluid level and condition.
   a. If low, fill with MERCON® Automatic Transmission Fluid (XT-2-QDX) to the proper level and check for leakage.
   b. If a pan gasket leak is the only concern, DO NOT call the toll-free number. Service as required and follow all the normal service procedures as outlined in the appropriate Workshop Manual.
2. Check the harness connectors for proper installation at the Digital Transmission Range (DTR) sensor, solenoid body case connector, Turbine Speed Sensor (TSS), and, if equipped, the Output Shaft Speed (OSS) sensor and Vehicle Speed Sensor (VSS).
3. Perform on-board diagnostic tests and record all Diagnostic Trouble Codes (DTCs).
4. If no fault codes are present, go to Step 5. If fault codes are present, perform the required pinpoint tests as directed in the Powertrain Control/Emissions Diagnosis (PC/ED) Service Manual or Workshop Manual for any fault codes received. Repair only the non-transmission codes and verify the transmission symptom still exists.
5. If the transmission symptom still exists, refer to the diagnosis by symptom in the Workshop Manual to determine if the concern is internal to the transmission.

NOTE
ALL DIAGNOSTIC INFORMATION (FLUID LEVEL AND CONDITION, DIAGNOSTIC TROUBLE CODES, TEST RESULTS, TRANSMISSION CONCERN AND TRANSMISSION TAG INFORMATION MUST BE RECORDED BEFORE CALLING THE TOLL-FREE NUMBER.

6. If the transmission requires service, call Ford Motor Company toll-free at 1-800-543-8742 between 8:00AM and 4:30PM EST (U.S. and Canadian dealers only).
7. This orange tag will be void after December 31, 2000. After this void date, do not call the toll-free number; repair as required.

NOTE
DO NOT DISASSEMBLE OR REPAIR THE TRANSMISSION (OTHER THAN DESCRIBED IN THIS TSB) PRIOR TO CALLING THE TOLL-FREE NUMBER.

PART NUMBER	PART NAME
XT-2-QDX	MERCON® Automatic Transmission Fluid (ATF)

Article No. 99-21-11 Cont'd.

OTHER APPLICABLE ARTICLES: NONE
WARRANTY STATUS: Eligible Under The Provisions Of Bumper To Bumper Warranty Coverage

OPERATION	DESCRIPTION	TIME
992111A	Check And Record Transmission Fluid Level And Condition, Add Fluid If Required	0.3 Hr.
992111B	Repair Pan Gasket As Required - Clean Or Repair As Outlined In The Appropriate Waorkshop Manual	0.9 Hr.
992111C	Additional Time To Check Transmission Harness Connections For Looseness And Check And Record DTCs If Required	0.5 Hr.
992111D	For Transmission Diagnostics And Diagnostic Repairs, Use "A" Time As Outlined In The Warranty And Policy Manual	

DEALER CODING

BASIC PART NO.	CONDITION CODE
7000	42

OASIS CODES: 501000, 502000, 503000, 503300, 504000, 510000, 590000

Figure 1 - Article 99-21-11