01B78 Instrument Panel Delamination on all 1999 and 2000 MY Contour and Mystique Vehicles – Previous Labor Operations

Replacements Dated Prior to May 28, 2002 only The following labor operations must be used on different repair orders. This is to allow closing the repair order that the instrument panel was ordered with.		
Replace Instrument Panel	01B78C	3.7 Hours
Inspect IP – Requires IP Ordering and Replacement*	01B78E	0.2 Hours

*A physical inspection and measurement of the customers' instrument panel must be performed prior to replacement authorization. Dealer must use 01B78E to claim for inspection of warpage if a replacement IP is ordered for installation at a subsequent date. Subsequent repair order must reference original repair order.

Repairs Dated Prior to June 10, 2002 only		
Perform Instrument Panel Repair per 01B78 Supplement #1 (for Repair Dates Prior to June 10, 2002)	01B78F	2.1 Hours

© Copyright 2001 Ford Motor Company