Ford Motor Company

A. R. O'Neill
Director
Vehicle Service and Programs
Ford Customer Service Division

Ford Motor Company
P. O. Box 1904
Dearborn, Michigan 48121

September 2000

TO: All Ford and Lincoln Mercury Dealers

SUBJECT: Safety Recall 00S16: Certain 1996 through 2000 Model Year Crown Victoria, Grand Marquis & Town Car Vehicles Which Had the **Right** Front Safety Belt Retractor Replaced in Service – Safety Belt Retractor Inspection and, If Necessary, Replacement

REF:
1. Dealer Announcement dated 12/17/98, Lincoln Commitment Special Handling Procedure (Attachment IV)
2. Safety Recall 00S15 dated 9/00, Certain 1996 through 2000 Model Year Crown Victoria, Grand Marquis & Town Car Vehicles Which Had the Left Front Safety Belt Retractor Replaced in Service – Safety Belt Retractor Inspection and, If Necessary, Replacement

NOTE: Some of the vehicles affected by Safety Recall 00S16 may also be included in Safety Recall 00S15. To minimize customer inconvenience, please check OASIS and, if applicable, perform Safety Recall 00S15 when the vehicle is in your dealership for Safety Recall 00S16.

AFFECTED VEHICLES

Certain 1996 through 2000 model year Crown Victoria, Grand Marquis and Town Car vehicles, which had the right front safety belt retractor replaced in service and meet both of the following two requirements:

- Retractor replacement dates from January 1, 2000 through June 13, 2000.
- Right front retractor assembly built from June 1, 1998 through May 21, 2000.

REASON FOR RECALL

Federal Motor Vehicle Safety Standard (FMVSS) No. 209 specifies that safety belt assemblies with emergency locking retractors must meet limits on webbing extension. Some of the affected vehicles had the right front safety belt replaced in service with a retractor assembly that may not fully meet FMVSS No. 209 web extension limit requirements.

SERVICE ACTION

The dealer must inspect the right front safety belt retractor build date label and, if necessary, replace the retractor on all affected vehicles identified by Ford Motor Company through its warranty system.

In addition, if the dealer has knowledge of a vehicle, which possibly was serviced between January 1, 2000 through June 13, 2000 with an affected right front safety belt retractor outside the vehicle warranty period (includes vehicles serviced under any service protection plan), the dealer should contact the owner, provide a copy of the attached owner notification letter and schedule a service appointment. In these instances, it will be necessary to call the Recall Hotline at 1-800-325-5621 to obtain approval to submit the claim.

LINCOLN COMMITMENT SPECIAL HANDLING PROCEDURE

(For Town Car Owners Only)

The Lincoln Commitment Special Handling Procedure has been activated for all Lincoln owners affected by this recall. Please see dealer announcement dated 12/17/98, Lincoln Commitment Special Handling Procedure (Attachment IV). The special handling procedure provides additional allowance to enable dealers to offer Lincoln owners convenient vehicle handling.

Lincoln Mercury is asking for your support and the cooperation of your sales and service teams to make this a positive experience for our Town Car customers, many of whom are new to the Lincoln family.

ATTACHMENTS

Attachment I: Administrative Information
Attachment II: Labor Allowances and Parts Ordering Information
Attachment III: Technical Information
Attachment IV: Lincoln Commitment Special Handling Procedure Announcement Letter
Customer Notification Letter

QUESTIONS?

Claims Information:……...1-800-423-8851
Other (Dealer Only) Recall Questions:……...1-800-325-5621

Sincerely,



Ann O'Neill
Director
Vehicle Service and Programs

Safety Recall 00S16

Certain 1996 through 2000 Model Year Crown Victoria, Grand Marquis & Town Car Vehicles Which Had the **Right** Front Safety Belt Retractor Replaced in Service
Safety Belt Retractor Inspection and, If Necessary, Replacement

OASIS

You must use OASIS to determine if a vehicle is eligible for this recall.

PLEASE NOTE

Correct all affected vehicles in stock before delivery. Federal law requires dealers to complete any outstanding safety recall service before a vehicle is delivered to the buyer or lessee. Violation of this requirement by a dealer could result in a civil penalty of up to $1,100 per vehicle.

PROMPTLY CORRECT

Promptly correct all affected vehicles on the VIN list provided in the Ford Dealership Consolidated Communicator (FDCC) and other eligible vehicles, which are brought to your dealership.

DEALER-OWNER CONTACT

Owners of affected vehicles according to Ford Motor Company records will be notified with the attached owner letter. If you have knowledge of an owner with an affected vehicle that did not receive a notification letter, contact that owner, give the owner a copy of the owner letter and arrange for a service date.

Note: Town Car owners should receive the " Lincoln Commitment Special Handling Procedure". Before calling Town Car owners, review Attachment IV to familiarize yourself with this special handling procedure.

REGIONAL CONTACT

Advise regional office if an owner:

- cannot be contacted.
- does not make a service date.

CLAIMS PREPARATION AND SUBMISSION

- Enter claims using DWE.
- Refer to ACESII manual for claims preparation and submission information.
- To claim for the "Lincoln Commitment Special Handling" on Town Car vehicles, follow the instructions on page two of Attachment IV.

RENTAL CARS

If the safety belt requires replacement, Ford will pay for a rental vehicle except for fuel, which will be at the owner's expense. A rental vehicle should be provided only while the owner's vehicle is at the dealership for the safety belt replacement. Follow Extended Service Plan (ESP) guidelines for rental dollar amounts. Enter the word "LOANER" plus the number of days the vehicle was used in the Miscellaneous Expense area of the recall claim.

Note: Town Car owners should receive the "Lincoln Commitment Special Handling Procedure". Before calling Town Car owners, review Attachment IV to familiarize yourself with this special handling procedure.

PARTS RETENTION

Follow the provisions of the Warranty and Policy Manual for "Parts Retention and Return Procedures".

Safety Recall 00S16
Certain 1996 through 2000 Model Year Crown Victoria, Grand Marquis & Town Car Vehicles Which Had the **Right** Front Safety Belt Retractor Replaced in Service
Safety Belt Retractor Inspection and, If Necessary, Replacement

LABOR ALLOWANCES

Description	Labor Operation	Labor Time
Inspect Right Front Safety Belt Build Date Code and Release Vehicle	00S16A	0.2 Hours
Inspect Right Front Safety Belt Build Date Code and Replace Safety Belt	00S16B	0.4 Hours
Administrative Allowance	Misc. Expense Code "ADMIN"	0.1 Hour
* Lincoln Commitment Special Handling:	Misc. Expense Code "LCHP"	See Attachment IV

* Lincoln Commitment Special Handling does not apply to vehicles in dealer stock.

PARTS REQUIREMENTS

Parts Ordering Information

Parts will not be direct shipped for this recall. Order your parts requirement through normal order processing channels as noted below:

Stock Orders	Effective immediately	Normal order process
Interim Orders	Effective immediately	Normal order process
Emergency Orders	First 30 days after launch	Call 1-800-325-5621
Emergency Orders	31 days after launch	Normal order process

NOTE: Please use the chart below only until the next publication of the Service Parts Catalog (September, 2000).

Table 1 – Crown Victoria/Grand Marquis				
Model Year	**Right Front Safety Belt Part Number**	**Color**	**Interior Trim Code 2nd Digit (X<u>X</u>)**	**Notes**
96	F6AZ-54611B08-BAC	Saddle	S	
96	F6AZ-54611B08-BAD	Cordovan	N	
96	F6AZ-54611B08-BAA	Portofino Blue	P	
97	F7AZ-54611B08-BAA	Denim	D, K	
96/97	F6AZ-54611B08-BAB	Willow	G, L, S	

Table 1 – Crown Victoria/Grand Marquis (continued)				
Model Year	**Right Front Safety Belt Part Number**	**Color**	**Interior Trim Code 2nd Digit (X<u>X</u>)**	**Notes**
97/98	F7AZ-54611B08-BAB	Prairie Tan	Y, S	
98	F7AZ-54611B08-BAC	Truffle	T	
96/98	F7AZ-54611B08-BAE	Graphite	2, X, M	
98	F7AZ-54611B08-BAD	Dark Denim Blue	R	
00	YW7Z-54611B08-AAH	Med./Lt. Parchment	G	
99/00	YW7Z-54611B08-AAD	Med. Parchment	H, J	
99	YW7Z-54611B08-AAJ	Parchment	G	
99/00	YW7Z-54611B08-AAE	Deep Slate Blue	R, K	
99	YW7Z-54611B08-AAK	Graphite	2, X	
00	YW7Z-54611B08-AAG	Med. Graphite	2, X	
00	YW7Z-54611B08-AAF	Midnight Black	W	

Table 2 – Town Car				
Model Year	**Right Front Safety Belt Part Number**	**Color**	**Interior Trim Code 2nd Digit (X<u>X</u>)**	**Notes**
96/97	F6VZ-54611B08-BAA	Ivory	8, 5, 9	
97	F6VZ-54611B08-BAB	Prairie Tan	Y, T	
96/97	F6VZ-54611B08-BAC	Cypress	3, A	
96	F6VZ-54611B08-BAD	Saddle	S	
96/97	F6VZ-54611B08-BAE	Cordovan	N	
96/97	F6VZ-54611B08-BAF	Black	J	
96	F6VZ-54611B08-BAG	Portofino Blue	P	
96/97	F6VZ-54611B08-BAH	Light Graphite	2, X, 1	
97	F6VZ-54611B08-BAJ	Denim	D, 4	
98	F8VZ-54611B08-BAA	Ivory	9	
98	F8VZ-54611B08-BAB	Prairie Tan	Y	
98	F8VZ-54611B08-BAC	Dark Denim Blue	R	
98	F8VZ-54611B08-BAD	Light Graphite	2, X	

Table 2 – Town Car (continued)				
Model Year	**Right Front Safety Belt Part Number**	**Color**	**Interior Trim Code 2nd Digit (X<u>X</u>)**	**Notes**
98	F8VZ-54611B08-BAE	Midnight Black	W	
99	XW1Z-54611B08-BAA	Light Parchment	G	
00	XW1Z-54611B08-BAF	Med. Parch/Lt. Parch	G	Before Feb. 2000
00	XW1Z-54611B08-BAG	Med. Graph/Lt. Graph	2, X	Before Feb. 2000
99/00	XW1Z-54611B08-BAB	Med. Parchment	H	Excl. Executive Series
99/00	XW1Z-54611B08-BAC	Dark Denim Blue	R	
99	XW1Z-54611B08-BAD	Light Graphite	2, X	
99/00	XW1Z-54611B08-BAE	Midnight Black	W	Excl. Executive Series
00	YW1Z-54611B08-BAA	Med. Parch/Lt. Parch	G	From Feb. 2000
00	YW1Z-54611B08-BAB	Med. Graph/Lt. Graph	2, X	From Feb. 2000
00	YW1Z-54611B08-BAC	Med. Parchment	H	Executive Series
00	YW1Z-54611B08-BAD	Dark Denim Blue	R	
00	YW1Z-54611B08-BAE	Midnight Black	W	Executive Series

DEALER PRICE

For latest prices, refer to:

- DOES II
- Updated Price Book

EXCESS STOCK RETURN

Excess stock returned for credit must have been purchased from Ford Customer Service Division in accordance with Policy Procedure Bulletin 4000.

Program Announcement Letter
Lincoln Commitment Special Handling

Ford Customer Service Division

Ford Motor Company
P.O. Box 1904
Dearborn, Michigan 48121

December 17, 1998

To: All Lincoln Mercury and Ford Dealers

cc: Parts Managers
Service Managers

Subject: Announcing Lincoln Commitment Special Customer Handling Procedure for Certain Recalls and Owner Notification Programs

As part of our ongoing commitment to Lincoln customers, we are pleased to announce the Lincoln Commitment Special Customer Handling Procedure to provide additional dealer compensation for certain Recalls and Owner Notification Programs(ONP's) that affect Lincoln brand vehicles.

This additional compensation is being provided to allow dealers to provide personalized service designed to make the recall repair a positive experience for the Lincoln customer, many of whom are new to the Lincoln family.

Each Recall/ONP Bulletin affecting Lincoln vehicles will indicate whether the Lincoln Commitment Special Customer Handling Procedure is authorized; please note that not every Recall/ONP will qualify for this procedure and that the procedure will not be communicated to customers as a normal benefit of the Lincoln Commitment Program. Special handling and claiming instructions are included on the attached page. This program will apply only to Lincoln vehicles which have been delivered to customers.

We ask you to make maximum usage of these special enhancements to the Lincoln Commitment Program when applicable. Thank you in advance for your support of this program and our commitment to surprise and delight our Lincoln customers.

/O.S.B./
Mark Hutchins
President
Lincoln Mercury

/O.S.B./
M. D. Jordan
Executive Director
Ford Customer Service Division
North America

If Dealer Picks up and Returns Vehicle for Customer:

Special Service	Dealer Compensation	Claim Procedure
• Pick up the customer's vehicle (at a location of their preference such as home or place of business) and return after repair* • Drop off comparable loaner vehicle • Refill fuel tank • Wash and vacuum vehicle • Return vehicle to customer after repair is completed	Up to 2 hours additional labor (converted to a dollar amount) plus actual cost of fuel and wash/vacuum Note: Labor time to fill tank and wash/vacuum has been included in 2 hour allowance Labor subject to time recording procedures as outlined in Warranty & Policy Manual	Submit total dollar value (labor+fuel+wash/vacuum) using Misc. Expense Code "LCHP" EXAMPLE (using example labor rate of $58/hour and fuel cost of $1.05/gallon): 1.2 hrs. labor* = $69.60 9.0 gals fuel = 9.45 Wash/vacuum = 3.50 Total Submitted = $82.55 *travel time+fueling/washing labor
Provide comparable loaner vehicle to customer when vehicle is picked up	Actual cost up to a maximum of $35 per day for a Lincoln loaner or up to $28 per day for a Mercury or Ford loaner (This does not count against TAP allocation)	Submit up to 3 days maximum using "LOANER" (if additional days are required, call 1-800-325-5621 for authorization)
Perform Recall/ONP repair at dealership	Inspection/repair labor allowance as specified in Recall/ONP Bulletin	See applicable Recall/ONP Bulletin

*Or repair on-site if appropriate; if on-site repair is performed, rental charges do not apply.

If Customer Brings Vehicle to Dealer:

Special Service	Dealer Compensation	Claim Procedure
Perform Recall/ONP repair at dealership	Inspection/repair labor allowance as specified in Recall/ONP Bulletin	See applicable Recall/ONP Bulletin
Provide comparable loaner vehicle to customer	Actual cost up to a maximum of $38 per day for a Lincoln loaner or up to $28 per day for a Mercury or Ford loaner (This does not count against TAP allocation)	Submit up to 3 days maximum using "LOANER" (if additional days are required, call 1-800-325-5621 for authorization)
Refill fuel tank and wash/ vacuum vehicle	Up to 0.5 hour additional labor (converted to a dollar amount) plus actual cost of fuel and wash/vacuum	Submit total dollar value (labor+fuel+wash/vacuum) using Misc. Expense Code "LCHP"

Ford Motor Company

Ford Motor Company
P. O. Box 1904
Dearborn, Michigan 48121

October 2000

00S16

Mr. John Sample
123 Main Street
Anywhere, USA 12345

Your Vehicle Identification Number: 12345678901234567

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

Ford Motor Company has decided that certain 1996 through 2000 model year Crown Victoria, Grand Marquis and Town Car vehicles that recently had the right front safety belt replaced in service may fail to conform to certain requirements specified in the Federal Motor Vehicle Safety Standard (FMVSS) No. 209 "Seat Belt Assemblies".

We apologize for this situation and want to assure you that with your assistance we will correct this condition. Our commitment, together with Ford and Lincoln Mercury dealers, is to provide you with the highest level of service and support possible.

What the non-compliance issue is….	Federal Motor Vehicle Safety Standard (FMVSS) No. 209 specifies that safety belt assemblies with emergency locking retractors must meet limits on webbing extension. Ford Motor Company records indicate that your vehicle had the right front safety belt replaced in service with a retractor assembly that may not fully meet FMVSS No. 209 web extension limit requirements.
What Ford Motor Company and your dealer will do...	At no charge to you, your dealer will inspect your vehicle's right front safety belt retractor build date and, if necessary, replace the retractor. Dealers currently have instructions and parts ordering information.
How long will it take?	The time needed for this repair is less than one-half day. However, due to service scheduling requirements, your dealer may need your vehicle for a longer period of time.
Will a rental vehicle be provided?	If the right safety belt assembly requires replacement after inspecting your vehicle, the safety belt will need to be ordered. In these cases, your dealer is authorized to provide a free rental vehicle (except for fuel) until repairs can be completed.
What we are asking you to do…	Call your dealer without delay. Ask for a service date for Safety Recall 00S16. When you bring your vehicle in, show the dealer this letter. If you misplace this letter, your dealer will still do the work, free of charge.

If you've changed address or sold the vehicle…

Please fill out the enclosed prepaid postcard and mail it to us if you have changed address or sold the vehicle.

If you have concerns…

If you have trouble getting your vehicle repaired promptly and without charge, please contact the Ford Motor Company Customer Assistance Center and one of our representatives will be happy to assist you:

CALL: (800) 392-3673
(800) 232-5952 (TDD for the Hearing Impaired)

Office Hours: (Eastern Standard Time)

Monday-Friday: 8am - 11pm
Saturday: 9am - 6pm

or you may contact us through the Internet at:
www.ownerconnection.com
Our current response time to Internet inquiries is three business days.

You also may send a complaint to the Administrator, National Highway Traffic Safety Administration, 400 Seventh Street, S. W., Washington, D. C. 20590 or call the toll free Auto Safety Hotline 1-800-424-9393 (Washington, D. C. area residents may call 1-202-366-0123).

Quality Care service is there for you all year round.

QualityCare™ at your service

Quality Care is the commitment of Ford Motor Company and its dealerships to provide you with a superior service and ownership experience. While we regret the inconvenience caused by this program, we stand committed with our dealers to assist you with all of your automotive service needs. With our nationwide dealer network, we're here to ensure you receive Quality Care service so that your vehicle maintains peak performance throughout your ownership experience.

We pride ourselves on becoming the world's leading consumer company for automotive products and services. Again, we are sorry for the inconvenience. Thank you for your attention to this important matter.

Sincerely,



Ann O'Neill
Director
Vehicle Service and Programs